04/08/2013 OperationControlTicket vers. 1 CLD9 Original Page 1

Order 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Order type T180 EL TRANS EXPENSE RECURRING

Status REL NMAT PRC SETC

User Status UNSC

Start date 07/30/2013 End date 07/31/2013

FunctLocation ETL. 1450. POLE. WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Equipment 40582705 009/113A SINGLE WOOD POLE

MaintPlanGroup TLP ECES

 MainWrkCenter
 SACTO
 ECES
 Sacramento

 Priority
 E
 E - Schd Compl Yr 0

MaintenancePlan MaintPlanItem Revision No.

Partner ALCI JO

Address Luz Angie L.

Phone 530/906-0293

Class ETLEOP Electric Transmission Line Equipment 002

ETL ACCESSIBILITY LIGHT EQP (CREW CABS, PICKUPS)

ETL FRAMINGCONFIG 3 POLE SINGLE VERTICAL

ETL_UNDERBUILT YES

Class ETL_POLE ETL-POLE 002
ETL_ACCESSIBILITY LIGHT EQP (CREW CABS, PICKUPS)

ETL FRAMINGCONFIG 3 POLE SINGLE VERTICAL

ETL_UNDERBUILT YES

LATITUDE 39.321025000000 LONGITUDE -120.621467000000

Operation 0004 Transmission OH Detailed Inspection

Work center ET_TMAN1 ECES ELECTRIC TROUBLEMAN TRANSMISSION

Control key INDT CompConf No. 18344559

Operation key ETL03 Milestone
Work 12 MIN Activity type MO
Daystion 1 DAY Number 1

Duration1DAYNumber1EarlStartDate07/30/2013Start time00:00:00LateEndDate07/31/2013End time00:00:00

Actual work 0 MIN Total buffer 0 MIN

NAME AND LAW ID OF OCR: BEARD WAS SIGNATURE OF OCR: BEARD
SIGNATURE OF SUPERVISOR: OTD & 13

Transmission Line Inspection Datasheet

Inspector Name :_ Wiles Inspected:

DEMED Date Inspection Completed:

PATR/INSP 10058 DRUM-SUMMIT #2

Work Center : ET_TMAN1 : BFZ

> # Structures Inspected: 79 ELECTRIC TROUBLEMAN TRANSMISSION Detailed Ground Inspections

High Impact ISO:

: ETL.1450.POLE.WOOD10058 DRUM-SUMMIT #2-WOOD POLE # Struct Order: 449

PATR/INSP 10058 DRUM-SUMMIT #2 (Annual Air Patrols)

07/18/2012 07/20/2012

Line Last Inspected: 41619467

Oper Volt Funct Loc

: 115 KV

Line Miles : 28 M

Inspection Findings Data

	#					Hrs	Yes/No/Hot	#
7/16/13	27/623	1507	web3	UI.	BENT DAMPER	ı		107062935
1	Wan Alos	Alob	CHID	71	AUTO SPLICE GUY WIRE			107063156
	,							
			1					
				,	•			
	-							



04/08/2013 OperationControlTicket vers. 1 CLD9 Original Page 1

Order 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Order type T180 EL TRANS EXPENSE RECURRING

Status REL NMAT PRC SETC

User Status UNSC

Start date 07/30/2013 End date 07/31/2013

FunctLocation ETL. 1450. POLE. WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Equipment 40582705 009/113A SINGLE WOOD POLE

MaintPlanGroup TLP ECES
MainWrkCenter SACTO ECES Sacramento

MainWrkCenterSACTOECESSacramentoPriorityEE - Schd Compl Yr 0

MaintenancePlan MaintPlanItem Revision No.

Partner ALCI JO

Address Luz Angie L.

12345

Phone 530/906-0293

Class ETLEQP Electric Transmission Line Equipment 002

ETL_ACCESSIBILITY LIGHT EQP (CREW CABS, PICKUPS)

ETL FRAMINGCONFIG 3 POLE SINGLE VERTICAL

ETL UNDERBUILT YES

LATITUDE 39.321025000000 LONGITUDE -120.621467000000

Class ETL_POLE ETL-POLE 002
ETL_ACCESSIBILITY LIGHT EQP (CREW CABS, PICKUPS)

ETL_FRAMINGCONFIG 3 POLE SINGLE VERTICAL

ETL_UNDERBUILT YES

LATITUDE 39.321025000000 LONGITUDE -120.621467000000

Operation 0004 Transmission OH Detailed Inspection

Work center ET TMAN1 ECES ELECTRIC TROUBLEMAN TRANSMISSION

Control key INDT CompConf No. 18344559

Operation key ETL03 Milestone

Work 12 MIN Activity type MO
Duration 1 DAY Number 1

 EarlStartDate
 07/30/2013
 Start time
 00:00:00:00

 LateEndDate
 07/31/2013
 End time
 00:00:00:00

Actual work 0 MIN Total buffer 0 MIN

NAME AND LAN ID OF OCR: K BIMSON RBBS

SIGNATURE OF OCR: RBM

SIGNATURE OF SUPERVISOR: DP 8 1 13

DATE

Transmission Line Inspection Datasheet

Inspector Name: K Bimsec Date Inspection Completed: 7-34-13

Miles Inspected : 3)

Structures Inspected: 253

Plan Group 41815880

Oper Volt Funct Loc

: 115 KV

PATR/INSP 10058 DRUM-SUMMIT #2 ET Poles

ETL.1450.POLE.WOOD10058 DRUM-SUMMIT #2-WOOD POLE Line Miles : 28 M

MAT Work Center

: ET_TMAN1 : BFZ

ELECTRIC TROUBLEMAN TRANSMISSION Detailed Ground Inspections : OSI

High Impact

Struct Order: 449

PATR/INSP 10058 DRUM-SUMMIT #2 (Annual Air Patrols)

07/18/2012 07/20/2012

Inspection Findings Data

Line Last Inspected: 41619467

mes2 F Breten	17-2013 ABIO CHILL F (EP) NEW-	mc25 F	31-13 13-159 CF14 CHIO F Auto and Splices	7.31.13 17-113C Swol CHOT F Theples Pole	7-31-13 9-102 C Smol mc23 F /Kephac File	7-31-13 9-1028 SWOI MCZ3 F Jake Folk	7.37-13 7-87 AGIO CHIY F PROPER Apriles	7-31-13 7-84 ABOG CHIO F Transfer gang	7-81 CFLO CHO8 F	7-31-13 1-16 CFILL CHIO F ANTO CAY SOLICE	7-31-13 1-140 AGOL CALD F Transfer gings	7-31-13 1-148 CFIY CHIO F Auto Guy SPING	7.31.13 1-14A CFIH CHIO F ANTO GUY SONICE	7-31-13 0-6 A510 MCOZ F INSHAN ANDER		pare tours perfect remains errorred commence
	_														Hrs	P S C
															Yes/No/Hot	Crearance
107062933	10706317	167059983	10706315	186550201	167059968	107059984	10706317	10706315	10706288	10706288	588490601	688690101	808290101	108 600001	#	NOCTATOR

Inspector Name : RBimsod

Date Inspected : Z-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

	Transchion Bogult	Attachments #
Desc of Tech ID	Inspection Result	Attachment Type/Owner Listed
Equip #		Accademient Type/Owner Histed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Unit 1 H of Debrokmonto.
000/001 WOOD POLE STRUCTURE	[//completed/no problems	Total # of Attachments:
40593968	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K002031	
39.256186000000		
-120.7662020000		make 1 B = 6 Determinants.
000/002 WDOD POLE STRUCTURE	[completed/no problems	Total # of Attachments:
40702390	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002032	
39.255631000000		
-120.7649720000		
000/003A SINGLE WOOD POLE	[] completed/no problems	Total # of Attachments:
40659113	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K002033	
39.255239000000		
-120.7638240000		
000/003B SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
42572743	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.255192000000		
-120.7638420000		
000/003C SINGLE WOOD FOLE	completed/no problems	Total # of Attachments:
42572744	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K00211	
39.255116000000		
-120.7638770000		
000/004 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments:
40771881	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K00203	4
39.254983000000		
-120.7625810000		
000/005 WDOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40761255	[]completed/new finding(s	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K00203	5
39.254953000000		
-120.7618850000		
000/006 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40828470	tocompleted/new finding(s	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: 02 Survey: K00203	
39.254972000000	I ristall New	A A-10 201
1-120.7605270000		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~

Inspector Name : R Bimson

Date Inspected : 7-31:13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
000/007 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments:
40826537	[]completed/new finding(s)	
3 POLE COUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspctd this patrol	
	Notes: '02 Survey: K002037	
39.255006000000		
-120.7598760000		
000/008 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40878342	completed/new finding(s)	
3 POLE COUBLE VERTICAL	[]pre-existing cond chked	
MEDIUM EOP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002038	
39.254776000000		
-120.7582460000		
000/009 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40862024	[]completed/new finding(s)	
2 POLE SUSP	Mpre-existing cond chked	
MEDIUM EOP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K002039	
39.254280000000	1 24 21 11	10.1
-120.7543000000	1 CH 31 04	VEH 75°
000/010 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40590170	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EOP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K002040	
39.253994000000		
-120.7521010000		
000/011 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40586191	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002041	
39.253865000000		
-120.7509780000		
000/012 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
42572858	[]completed/new finding(s)	
SUSPENSION (TWR)	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	5
39.253786000000		
-120.7499850000		
001/013 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40604671	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K00204	2
39.253535000000		
-120.7487070000		
001/014A SINGLE WOOD POLE	[]completed/no problems	Total # or Attachments:
40597040	Completed/new finding(s	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K00204	-
39.253679000000		10
-120.7464460000	AUTO GUY S	Plias

Inspector Name : RBimson

Date Inspected : 7.31.13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Dogg of Work ID	Inspection Result	Attachments #
Desc of Tech ID	THE PECCION VESUTE	Attachment Type/Owner Listed
Equip #		Accachiant Type, onner 1110000
Framing Config		
Access:	Notes	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
001/014B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572859	completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.253609000000	Auro guy spl	C 10 .
-120.7462910000		
001/014C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572861		
DOUBLE DEAD END	pre-existing cond chied	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.253567000000	- C.	عصواته و مد
-120.7462250000	Transfer guys	O NEW ANCKET
001/015A SINGLE WOOD POLE	[[completed/no problems	Total # Of Attachments:
40668112	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	/ not inspetd this patrol	
	Notes: '02 Survey: K002044	(CCG) LONGITUDE DATA FROM MASTER
39.254499000000		
-120.7456160000		
001/015B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572745	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
	()not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.254474000000		
-120.7455570000		
001/015C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572746	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
	[]not inspetd this patrol	<u> </u>
	Notes: '02 Survey: K002115	
39.254442000000	CH. 33'05"	VEH 33'05"
-120.7455180000	Ch. 33 03	VLA 30 00
001/016 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
4065 0 149	(x1completed/new finding(s)	
3 POLE TRAMP DOUBLE DEAD END	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002046	
39.255968000000	Auto Gny spli	CL.
-120.7447270000	Aut ond Still	
001/017A SINGLE WOOD POLE	i completed/no problems	Total # of Attachments:
40755366	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002047	
39.257961000000		
-120.7436430000		
001/017B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572863	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.257919000000		
-120.7436650000		

Inspector Name: R Bimson

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		· ·
HOST Tech ID/Equip #:	Notes	A.,
	110001	
Lat:		
Long:		Total # of Attachments:
001/017C SINGLE WOOD POLE	[/]completed/no problems	Total # or Attachments:
42572864	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.257955000000		
-120.7435550000		
001/018 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments:
40752035	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
LIGHT EQP (CREW CASS, FICHORS)	Notes: '02 Survey: K002048	
	Notes: 02 Survey. Nov2045	
39.258862000000		
-120.7428690000	116	Total # of Attachments:
001/019 WOOD POLE STRUCTURE	[/] completed/no problems	
40810266	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002049	
39.260187000000		
-120.7417100000		
001/020 WOOD POLE STRUCTURE	[completed/no problems	Total # of Attachments:
40826533	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002050	
39.261433000000	CH 419" 11	T 110.1 700
-120.7407690000	LH 49 /	7 1/217 /8
001/021 WOOD POLE STRUCTURE	(/completed/no problems	Total # of Attachments:
40870468	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EOP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	}
MEDIUM EQP (AERIAG DIFI, MINE IN	Notes: '02 Survey: K002051	
	Modes: Q2 Dulyej. Massass	
39.263030000000	<u></u>	
-120.7395560000	[]completed/no problems	Total # of Attachments:
0010/22 WOOD FOLE STRUCTURE		
40876957	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002052	
39.263507000000		
-120.7391920000		
002/023 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40618800	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K00205	3
39.264158000000		
-120.7387640000		
002/024 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40594582	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K00205	
39.265632000000		
-120.7374760000		

Inspector Name : RBim50~ Date Inspected : 7:31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Desc of fech in Equip #	Tribbeering Herman	Attachment Type/Owner Listed
Equip # Framing Config		
Access:	4	
HOST Tech ID/Equip #:	Notes	
	110001	
Lat: Long:		
002/025 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	
40660416	[]pre-existing cond chked	
2 POLE SUSP	[] not inspetd this patrol	
MEDIUM EQP(AERIAL LIFT; LINE TR	Notes: '02 Survey: K002055	(CCG) LONGITUDE DATA FROM MASTER
39.267501000000	Notice of the second	
-120.7364400000		
002/026 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40653619	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
MEDICAL DECAMANDE BEEN PROPERTY	Notes: '02 Survey: K002056	5
39.269637000000		
-120.7355880000		
002/027 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40751969	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
MENTON DAT (American	Notes: '02 Survey: K00205	7
39.270124000000		
-120.7354030000		
002/028 WOOD POLE STRUCTURE	[/jcompleted/no problems	Total # of Attachments:
40752037	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K00205	8
39.270650000000		
-120.7350310000		
002/029 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40810268	[]completed/new finding(s)
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K00205	9
39.272009000000		
-120.7344130000		
002/030A SINGLE WOOD POLE	[completed/no problems	Total # of Attachments:
40818745	[]completed/new finding(s	0
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: 102 Survey: K00206	0 7
39.273236000000	1 011 47	11" UEH 79°
-120.7339190000	1 CH . 12	
002/030B SINGLE WOOD POLE	[/] completed/no problems	Total # of Attachments:
42572865	[]completed/new finding(s	
DOUBLE DEAD END	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K00211	is
39.273228000000		
-120.7338980000		
002/030C SINGLE WOOD POLE	(/)completed/no problems	Total # of Attachments:
42572866	[]completed/new finding(s	5)
DOUBLE DEAD END	[]pre-existing cond chked	i
	[]not inspetd this patrol	
	Notes: '02 Survey: K0021	15
39.273208000000		
-120.7338650000		

Page 6

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

)rder : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name : R Bimson Date Inspected: 7-31-13

High Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		7-
Access:		
HOST Tech ID/Equip #:	Notes	
	Moces	
Lat:		
Long:		
002/031 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments:
40862274	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EOP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K002061	
39.273746000000		
		•
-120.7328140000	[]completed/no problems	Im-t-1 # +6 3-t1
002/032 WOOD POLE STRUCTURE	1	Total # of Attachments:
40862026	[]completed/new finding(s)	
2 POLE SUSP	Kipre-existing cond chked	
WEDIUM EQP(AERIAL LIFT; LINE TR	Ynot inspetd this patrol	
	Notes: '02 Survey: K002062	(CCG) LONGITUDE DATA FROM MASTER
39.274151000000	,	
-120.7321350000 .	,	
002/033 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40603786	[]completed/new finding(s)	
	1	
2 POLE SUSP	Mpre-existing cond chksd	
WEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survsy: K002063	
39.274995000000		
-120.7304480000		
003/034 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40590173	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
	1	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002065	
39.275823000000	CH 21 62	1171 776°
-120.7289000000	1 -11. 210	VEH 19°
003/035 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
10586192	[]completed/new finding(s)	
POLE SUSP	Opre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	/not inspetd this patrol	
	Notes: '02 Survey: K002066	
39.276726000000		
-120.7271510000	[1	Potent & of Athershapeta
)03/036A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
10660420	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[pre-existing cond chked	
MEDIUM EOP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
•	Notes: '02 Survey: K002067	
39.277182000000		·
.120.7264770000		
03/036B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
12572747	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[/pre-existing cond chked	
ANGEE 0-30 DEGREES	1 -	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
19.277185000000		
·120.7264510000		
103/036C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
:2572748	[]completed/new finding(s)	
NGLE 0-30 DEGREES	[pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	0
9.277154000000	111 12	VEN 80
120.7263830000	C.H 41 10	VEB 80
	•	

Inspector Name : RBMSON

Date Inspected : 7.31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
003/037 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40650152	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspctd this patrol	
	Notes: '02 Survey: K002068	
39.278658000000		
-120.7257010000		
003/038 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40751971	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K002069	·
39.280047000000		
-120.7250610000		Total a control of the control of th
003/039A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40771048	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	Opre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	([]not inspetd this patrol	
	Notes: '02 Survey: K002070	
39.281262000000		
- 120.7246410000		maked H of Shapehoomes.
003/039B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572867	[]completed/new finding(s)	
DOUBLE DEAD END		
	Notes: '02 Survey: K002115	
22 2211 2200000	Noces: 102 Survey: Rouzits	
39.281152000000		
-120.7245640000 003/039C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572868	[]completed/new finding(s)	,,
DOUBLE DEAD END	Mpre-existing cond chked	
BOODER DEAD BND	Inot inspetd this patrol	
	Notes: '02 Survey: K002115	
39.281147000000		
-120.7244880000		
003/040 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40828472	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002071	
39.281658000000		
-120.7232930000		
003/041 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40818175	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: 102 Survey: K002072	
39.282147000000		
-120.7218290000		
003/042 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40878344	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
20, 20,000,000,000	Notes: '02 Survey: K002073	
39.282894000000		
-120.7200020000		

Page 8

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name: RBimson

Date Inspected: 7-31-13

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	1.000	
Long: 003/043 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	TOTAL # OF ACCAMMENTS.
40869615		
2 POLE SUSP	pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002074	
39.283135000000		
-120.7190490000		1
003/044 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40618803	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EOP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002075	
39.283837000000		
-120.7171150000	/	
003/045 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40586194	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002076	
39.284153000000	0.1 -01	4
-120.7160710000	1. CU. 33 8	(16.14 87)
004/046 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40619814	[]completed/new finding(s)	TOTAL W OF THE WASHINGTON
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K002077	
39.284577000000		
-120.7150640000		
004/047 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
405939 6 9	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002078	
39.285092000000		
-120.7136430000		
004/048 WOOD POLE STRUCTURE	/] completed/no problems	Total # of Attachments:
40702392	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002079	
39.285861000000	51 5165 -	7 1 - 1 80
-120.7115650000	1 / CH 34 0 1	/ Uz H DU
004/049 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40669054	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
THE SHITT: THE TRANSPORT OF THE PARTY OF THE	Notes: 102 Survey: K002080	
28 28628680800	100es. 02 survey: Roozooo	
39.286396000000		· .
-120.7102970000	// 1 gamml of a 4 /	Total # of Attachments:
004/050A SINGLE WOOD POLE	lcompleted/no problems	TOCAL # OF MCCACHINERIOS:
40761541	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002081	
39.287111000000		
-120.7087290000		

Inspector Name : Rim60N

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

	12	1344
Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #: Lat:	Notes	
Long:		
004/050B SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
42572750	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.287080000000		
-120.7086980000		
004/050C SINGLE WOOD FOLE	completed/no problems	Total # of Attachments:
42572751	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.287038000000		
-120.7086220000		
004/051 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40761257	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002082	
39.288010000000		
-120.7079330000		
004/052 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40828474	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002083	
39.289473000000		
-120.7068140000 004/053 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40809757	[]completed/new finding(s)	iotal # of Medaciments;
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
FOOT ONL!	Notes: '02 Survey: K002084	
39.29074700000		4 200
-120.7057170000	1 Ent 53 01	1 154 85
004/054A SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
40878349	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K002085	
39.291974000000		
-120.7048690000		
004/054B SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572753	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.29194000000 0		
-120.7048670000		
004/054C SINGLE WOOD POLE	/completed/no problems	Total # of Attachments:
42572754	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.291904000000		j
-120.7048180000		

Inspector Name : RB/mso/ Date Inspected : 7.31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	,
Lat:		
Long:		
004/055A SINGLE WOOD POLE	Flcompleted/no problems	Total # of Attachments:
40869617	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
MEDIUM EOP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K002086	
39.292317000000	2 3 2	
-120.7044110000		
004/055B SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572755	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.292293000000		
-120.7043530000	/	
004/055C SINGLE WOOD POLE	[completed/no problems	Total # of Attachments:
42572756	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.292261000000		
-120.7042880000		
004/056 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40603704	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	·
FOOT ONLY	[] not inspctd this patrol	
	Notes: '02 Survey: K002087	
39.292961000000		
-120.7038600000		
004/057A SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
40586195	[]completed/new finding(s)	
3 POLE OOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K002088	
39.293639000000		
-120.7033220000		
004/057B SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572869	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.293632000000		
-120.7032860000		
004/057C SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572870	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[] not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.293580000000		·
-120.7032440000		
005/058 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40618806	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K002089	
39.294559000000		
-120.7025220000		

Inspector Name : PBimson

Date Inspected : 7.31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
_ · · · ·	Inspection Keadic	
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		l i
	Notes	
HOST Tech ID/Equip #:	Mores	
Lat:		
Long:		
005/059A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40586197	[]completed/new finding(s)	
3 FOLE DOUBLE VERTICAL	pre-existing cond chied	i
	[]not inspctd this patrol	
	Notes: '02 Survey: K002090	
	Mocco. Oz Boz Og. Moczos	
39.295608000000	Į.	1
-120.7017540000	J	
005/059B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572757	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	Mipre-existing cond chked	
ANGLE 0-30 DEGREES		
•	[]not inspetd this patrol	<u> </u>
	Notes: '02 Survey: K002115	
39.295566000000		
-120.7017390000		
	[]completed/no problems	Total # of Attachments:
005/059C SINGLE WOOD POLE		TOTAL # OF MCCGCHHEMES!
42572758	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	More-existing cond chked	
	[] not inspetd this patrol	
	Notes: *02 Survey: K002115	
	Noces: -02 Survey: R002113	
39.295565000000		
-120.7016790000	/	
005/060 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40650424	[]completed/new finding(s)	
2 POLE SUSP	{ pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K002091	
39.296478000000		
-120.7000250000		
005/061A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
		Today II de l'inches
40669056	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002092	· · · · · · · · · · · · · · · · · · ·
20 20714000000	1	
39.297140000000		
-120.6989130000		
005/061B SINGLE WOOD FOLE	[]completed/no problems	Total # of Attachments:
42572759	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
ANGLE 0-30 DEGREES		
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.297094000000		
-120.6988250000		
005/061C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
·	[]completed/new finding(s)	
42572760	1	
ANGLE 0-30 DEGREES	Vipre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.297077000000	•	
-120.6988210000		
005/062A SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40761543	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
The same of the sa	Notes: '02 Survey: K002093	
	Noces, uz Survey, Kouzuss	
39.297987000000		
-120.6982370000		

Inspector Name : RBV mon/ Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	/	
005/062B SINGLE WOOD POLE	/icompleted/no problems	Total # of Attachments:
42572761	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.297948000000		
-120.6981970000		
005/062C SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572762	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.297919000000		
-120.698166000 0		
005/063 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40771046	[]completed/new finding(s)	
2 PDLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002094	0
39.298487000000	CH. 22 07	3 UFH 550
-120.6968350000	[]completed/no problems	Total # of Attachments:
005/064 WOOD POLE STRUCTURE 40828476	[]completed/new finding(s)	Iblai # 61 Actachments:
TRAMP DOUBLE DEAD END	Apre-existing cond chked	
MEDIUM EOP (AERIAL LIFT; LINE TR	(]not inspetd this patrol	
MEDIUM EQP(AERIAN NIFI; NIME IR	Notes: '02 Survey: K002095	
39.299288000000	Rocco or Barroy, Mossons	
-120.6951310000		
005/065 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40806531	[]completed/new finding(s)	
2 POLE SUSP	pre-existing cond chked	•
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002096	
39.300096000000		
-120.693588000 0		<u></u>
005/066 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40878351	[]completed/new finding(s)	
2 POLE SUSP	pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT;LINE TR	1] not inspetd this patrol	
	Notes: '02 Survey: K002097	
39.300890000000		
-120.6920350000	/	
005/067 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40869619	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
20, 201 (05000000	Notes: '02 Survey: K002098	
39.301695000000		
-120.6906410000	[/]completed/no problems	Total # of Attachments:
005/068 WOOD POLE STRUCTURE 40603707	[]completed/no problems []completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP[AERIAL LIFT;LINE TR	[] not inspetd this patrol	
PRESTON BUE MONTAU BIF1; BIND IR	Notes: '02 Survey: K002099	
39.302511000000	January, Maray,	
-120.6890660000		

Inspector Name : R Binson

Date Inspected : 7-3:13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:	1	
Access:	Notes	
HOST Tech ID/Equip #:	Moces	
Lat:		
Long:		Total # of Attachments:
006/069 WOOD POLE STRUCTURE	[/] completed/no problems	
40584508	[]completed/new finding(s)	
2 FOLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K002100	
39.303409000000		
-120.6874810000		
006/070 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	
40582707	[]pre-existing cond chked	
2 POLE SUSP		
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002101	
39.304280000000	1011 75'00	" 15H 55"
-120.6858550000	GH. 53 02	<u> </u>
006/071 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40702401	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
MEDIUM EGP (MERIAD Ditt. Dina 11	Notes: '02 Survey: K002102	
	Notes: 02 Barrey: account	
39.305065000000		
-120.6843390000		Total # of Attachments:
006/072 WOOD POLE STRUCTURE	[/]completed/no problems	
40659114	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	1
MEDIUM EQP (AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: 102 Survey: K002103	
39.305958000000		
-120.6826120000		
006/073A SINGLE WOOD POLE	[/] completed/no problems	Total # of Attachments:
40765742	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
1.	[]not inspetd this patrol	
FOOT ONLY	Notes: 02 Survey: K00185	3
	Notes: 02 Barvey. Modes	,
39.306435000000		
-120.6819910000		Total # of Attachments:
006/073B SINGLE WOOD POLE	[/]completed/no problems	
42572763	[]completed/new finding(s	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K00211	5
39.306405000000		
-120.6819560000		
	[/]completed/no problems	Total # of Attachments:
006/073C SINGLE WOOD POLE	[]completed/new finding(s	
42572764	[]pre-existing cond chked	
ANGLE 0-30 DEGREES		
	[]not inspetd this patrol	
	Notes: '02 Survey: K00211	>
39.306382000000		
-120.6818830000		
006/074 WOOD POLE STRUCTURE	[]completed/nc problems	Total # of Attachments:
40771042	[]completed/new finding(s	
2 POLE SUSP	[pre-existing cond chked	
FOOT ONLY	Inct inspetd this patrol	
•	Notes: '02 Survey: K00185	4
39.306583000000		
-120.6803080000		
I-TV0.000000000		

Inspector Name : R Bimson

Date Inspected : 7-3i-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
006/075 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
1	[]completed/new finding(s)	
40828478	[]pre-existing cond chked	
2 POLE SUSP	1	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002104	
39.306786000000	04 34	03' UEH 65°
-120.6783650000	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
006/076 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40809759	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EOP (AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K002105	
39.306954000000		
-120.6767880000		
006/077 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40870449	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
	[]not inspetd this patrol	·
MEDIUM EQP(AERIAL LIFT; LINE TR	Notes: '02 Survey: K002106	
	MOEGA! -02 SULVEY: KOOZIOO	
39.307088000000		
-120.6752070000	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Total # of Attachments: 1
006/078 WOOD POLE STRUCTURE	[/completed/no problems	
40876959	[] completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002107	
39.307261000000		
-120.6735050000		
006/079 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments:
40618809	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
FOOT ONLY	Notes: '02 Survey: K002108	
	Notes: 02 Barroy. Motera	
39.307390000000		
-120.6717880000	[]completed/no problems	Total # of Attachments:
007/080 WOOD POLE STRUCTURE		
40618817	[]completed/new finding(s)	
2 POLE SUSP	pre-existing cond chked	
FOOT ONLY	Inot inspetd this patrol	
	Notes: '02 Survey: K00210	9
39.307598000000		
-120.6699190000		
007/081 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40602585	Mcompleted/new finding(s)
3 POLE DOUBLE VERTICAL	pre-existing cond chked	
FOOT ONLY Tramp -DDE	[]not inspetd this patrol	
1 Lowesh A - 2	Notes: '02 Survey: K00211	0
39.307757000000		
-120.6681620000	Bolton Com	nectors
007/082 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40660428	[]completed/new finding(s	
2 POLE SUSP	[]pre-existing cond chked	
	[] not inspetd this patrol	
MEDIUM EQP (AERIAL LIFT; LINE TR	Notes: '02 Survey: K00211	1
	Modes: 02 Bulvey. Modeli	- 0
39.308328000000	1 CN QL II	VEH 65°
-120.6670000000	CH. 36 11	The state of the s

Inspector Name: RB; msor

Date Inspected: 7-31-13

High Impact

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
007/083 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40669058	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002112	
39.308941000000		
~120.6656770000		
007/084 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40751973	completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	ļ
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002113	.
39.309613000000	I Transfer DE	To wend Archor
-120.6644130000		
007/085 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40755597	[]completed/new finding(s)	
2 POLE SUSP	flore-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
L	Notes: '02 Survey: K001855	
39.310610000000		
-120.6630440000	[]completed/no problems	Total # of Attachments:
007/086A SINGLE WOOD POLE	Completed/new finding(s)	The state of the s
40810270 3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
MEDIUM EOP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
MEDIOM EQF(RERIAD DIFI) LINE IX	Notes: '02 Survey: K001856	<u> </u>
39.311179000000		
-120.6623460000		
007/086B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572765	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	More-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.31114600000		
-120.6623280000		
007/086C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572766	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	☆ pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.311119000000		
-120.6623070000	[]completed/no problems	Total # of Attachments:
007/087 WOOD POLE STRUCTURE 40818177	(i
3 POLE DOUBLE VERTICAL	pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
1001 OH11	Notes: '02 Survey: K001857	
39.311753000000		
-120.6607650000	Replace MAKONIS	CH. 38 03" VEH 70"
007/088 WOOD POLE STRUCTURE	/]completed/no problems	Total # of Attachments:
40862276	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K001858	
39.312112000000	•	
-120.6590180000		
		

Page 16

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name: RBimson

Date Inspected: 7:31-13

Detailed Ground Inspections

- High Impact

Attachments # Inspection Result Desc of Tech ID Attachment Type/Owner Listed Equip # Framing Config Access: HOST Tech ID/Equip #: Notes Lat: Long: [completed/no problems Total # of Attachments: 007/089 WOOD POLE STRUCTURE []completed/new finding(s) 40876962 []pre-existing cond chked 2 POLE SUSP []not inspctd this patrol FOOT ONLY Notes: '02 Survey: K001859 39.312609000000 -120.6574810000 [/completed/no problems Total # of Attachments: 007/090 WOOD FOLE STRUCTURE []completed/new finding(s) 40618831 []pre-existing cond chked 2 POLE SUSP []not inspctd this patrol FOOT ONLY Notes: '02 Survey: K001860 39.312972000000 -120.6559970000 Total # of Attachments: completed/no problems 008/091 WOOD POLE STRUCTURE []completed/new finding(s) 40603710 []pre-existing cond chked 3 POLE DOUBLE VERTICAL []not inspctd this patrol Notes: '02 Survey: K001861 39.313392000000 -120.6545610000 Total # of Attachments: //completed/no problems 008/092 WOOD POLE STRUCTURE []completed/new finding(s) 40602587 []pre-existing cond chked 3 POLE DOUBLE VERTICAL [] not inspctd this patrol Notes: '02 Survey: K001862 39.313688000000 -120.6525980000 [/] completed/no problems Total # of Attachments: 008/093 WOOD FOLE STRUCTURE []completed/new finding(s) 40702394 []pre-existing cond chked 3 POLE DOUBLE VERTICAL []not inspctd this patrol Notes: '02 Survey: K001863 39.314082000000 -120.6509670000 Total # of Attachments: | | completed/no problems 008/094A SINGLE WOOD POLE []completed/new finding(s) (]pre-existing cond chked 3 POLE SINGLE VERTICAL []not inspctd this patrol Notes: '02 Survey: K001864 39.314326000000 VEH -120.6497060000 [/]completed/no problems 008/094B SINGLE WOOD POLE []completed/new finding(s) 42572767 []pre-existing cond chked ANGLE 0-30 DEGREES []not inspctd this patrol Notes: '02 Survey: K002115 39.314268000000 -120.6496910000 completed/no problems Total # of Attachments: 008/094C SINGLE WOOD POLE []completed/new finding(s) 42572768 []pre-existing cond chked ANGLE 0-30 DEGREES []not inspctd this patrol Notes: '02 Survey: K002115 39.314222000000 -120.6496750000

Inspector Name: RBinson

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
008/095 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40771883	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K001865	
39.315151000000		
-120.6477290000		
008/096 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40771044	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K001866	
39.316099000000		i i
-120.6458410000		
008/097 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40828480	[]completed/new finding(s)	·
3 POLE DOUBLE VERTICAL	pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K001867	
39.316983000000		
-120.6438350000	/	
008/098A SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
40826567	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspctd this patrol	
	Notes: '02 Survey: K001868	B
39.317982000000		A. A. A.
-120.6427440000		
008/098B SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572769	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K00211	5
39.317952000000 .		
-120.6426840000		
008/098C SINGLE WOOD POLE	[/lcompleted/no problems	Total # of Attachments:
42572770	[]completed/new finding(s	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K00211	5
39.317929000000		
-120.6426410000		
008/099A SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
40878353	[]completed/new finding(s	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K00186	9
39.320368000000		
-120.6416630000		
008/099B SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572771	[]completed/new finding(s	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	·
	Notes: '02 Survey: K00211	.5
39.320282000000		
-120.6415930000		

Page 18

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name : R Bimsav

Date Inspected : 7-31-13

High Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
	THE PECCION REDUCE	Attachment Type/Owner Listed
Equip #		ALCUCAMOID AJEO, OMAIL TOUR
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
008/099C SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572772	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.320242000000		
-120.6415680000		
008/100 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40869621	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
FOOT ONLY	Notes: '02 Survey: K001870	
22.22.24.20.20.0		
39.320904000000		
-120.6402450000	Vicompleted/no problems	Total # of Attachments:
008/101 WOOD POLE STRUCTURE	[]completed/new finding(s)	
40590176	[]pre-existing cond chked	
2 POLE SUSP		
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001871	
39.321728000000		
-120.6385570000		
009/102A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40618835	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
i	Notes: '02 Survey: K001872	
39.322713000000		
-120.6367950000		
009/102B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572774	Completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.322641000000	perhace ().	
-120.6368160000	per ace Co	
009/102C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572775	Micompleted/new finding(s)	
ANGLE 0-30 DEGREES]pre-existing cond chked	
ANGLE U-30 DEGREES	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
	Notes: 102 Survey: MODELLE	$O_{\mathcal{A}} = O_{\mathcal{A}} = O_{\mathcal{A}}$
39.322589000000	Replace	- 40 m
-120.6368010000	[/]completed/no problems	Total # of Attachments:
009/103 LATTICE STEEL TOWER, SW	[]completed/new finding(s)	
40602591		
FIELD SWITCH STRUCTURE	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
1	Notes: '02 Survey: K00187	5
39.322574000000		
-120.6364430000		
009/104 WOOD FOLE STRUCTURE	//completed/no problems	Total # of Attachments:
40702425	[]completed/new finding(s	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K00187	4
39.322229000000		
-120.6343550000		

Inspector Name : RBimson

Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
009/105 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40650153	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001875	
39.321862000000		
-120.632822000 0		
009/106 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40771897	[]completed/new finding(s)	
2 POLE SUSP	(]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001876	
39.321503000000		
-120.6307220000		
009/107 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40771050	[]completed/new finding(s)	, 52 11000000
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
BIGHT LOP (CREW CABS, FICKOPS)	Notes: '02 Survey: K001877	
39.321278000000	Moces: 102 Survey. Modisir	1
	() 4 4 4 1	1 ()EH 80°
-120.629205000D	[/]completed/no problems	Total # of Attachments:
009/108A SINGLE WOOD POLE	{ completed/new finding(s)	Total # Of Accasiments:
40819358	_	
3 POLE SINGLE VERTICAL	()pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspctd this patrol	
·	Notes: '02 Survey: K001878	
39,321071000000		
-120.6276900000		
009/108B SINGLE WOOD POLE	[[] completed/no problems	Total # of Attachments:
42\$72777	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.320976000000		
-120.6277330000		···
009/108C SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572778	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.320924000000		
-120.6277530000		
009/109 WOOD FOLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40826559	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	pre-existing cond chked	
FOOT ONLY	I]not inspetd this patrol	
	Notes: '02 Survey: K001879	
39.321007000000		
-120.6263150000		
009/110 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40862278	[/completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	Vipre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001880	
39.320958000000		
-120.6245340000		

Inspector Name: RBimson

Date Inspected: 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
	Notes	
Lat:		
Long:	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Total # of Attachments: 1
009/111 WOOD POLE STRUCTURE	[]completed/no problems	
40876990	[]completed/new finding(s)	D151-0310456 1
2 POLE SUSP	Apre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K001881	
39.320976000000	062-2-	===2
-120.6231850000		
009/112 WOOD POLE STRUCTURE	[./completed/no problems	Total # of Attachments: 1
40618837	[[completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K001882	
39.320999000000		
-120.6220240000		
009/113A SINGLE WOOD POLE	(completed/no problems	Total # of Attachments: 1
40582705	[]completed/new finding(s)	DIST-0310456 1
· ·	[]pre-existing cond chked	
3 POLE SINGLE VERTICAL	[]not inspetd this patrol	
LIGHT EQP (CREW CABS, PICKUPS)	Notes: '02 Survey: K001883	
	NOCES; 02 Balvey. Motors	•
39.32102500000		
-120.6214670000	[/completed/no problems	Total # of Attachments:
009/113B SINGLE WOOD POLE		"
425 72779	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K00211	5
39.320993000000		
-120.6214540000		
009/113C SINGLE WOOD POLE	[completed/no problems	Total # of Attachments:
42572780	Completed/new finding(s	
ANGLE 0-30 DEGREES]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K00211	
39.320928000000	0.10	
-120.6214330000	1 Replace Po	LE
009/114 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
40681165	[]completed/new finding(s	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
FOOT ONLY	Notes: '02 Survey: K00188	
	10000 02 Barrell 100100	
39.321041000000		
-120.6209210000	[/]completed/no problems	Total # of Attachments: 1
009/115 WOOD POLE STRUCTURE	[]completed/new finding(s	
40669060		
2 POLE SUSP	[]pre-existing cond chked	•
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K00188	d d
39.321476000000		
-120.5188260000		
010/116 WOOD POLE STRUCTURE	/_lcompleted/no problems	Total # of Attachments: 1
40603712	[]completed/new finding(s	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K00188	36
39.321726000000	_	
05.521,200000		
-120.6171320000		

Inspector Name : 7 Birmson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Inspection Reduct	Attachment Type/Owner Listed
Framing Config		The caching 1990, on act labour
Access:		
HOST Tech ID/Equip #:	Notes	
	Moces	
Lat:		
Long:		
010/117 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40602617	£ 100m2mona, man =====3 (=)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K001887	
39.321890000000	04 37 05"	1104 700
-120.6158820000	CH 34 05	UEA 70°
010/118 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40660433	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	Mpre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001888	<u></u>
39.322186000000		
-120.6145050000		
010/119A SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments: 1
40650155	[]completed/new finding(s)	
	-	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]nbt inspetd this patrol	
	Notes: '02 Survey: K001889	
39.322581000000		
-120.6130360000	_/	
010/119B SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572782	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.32252900000		
-120.6130030000		
010/119C SINGLE WOOD POLE	[/] completed/no problems	Total # of Attachments:
42572783	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.322438000000		
-120.6129530000		
010/120 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
•	[]completed/new finding(s)	
40751975		MAGI-0310436 T
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
20.2020000000000	Notes: '02 Survey: K001890	
39.323227000000		
-120.6123110000		Imperson the Company of the Company
010/121A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40752039	[]completed/new finding(s)	DIST-0310456 1
3 POLE SINGLE VERTICAL	pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	<u> </u>
	Notes: '02 Survey: K001891	
39.323819000000	1011 47 25	11512 700
-120.6118190000	14.76 OC	VETI 10
010/121B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572784	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	tore-existing cond chked	
	[/]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.323812000000		

Inspector Name : RBimson Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

High Impact

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
	Imprection Kenaic	Attachment Type/Owner Listed
Equip #		Accaemment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
010/121C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
· ·		TOTAL W OF ACCOMMENCE.
42572785	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.323748000000		
-120.6117950000		
010/122A SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40810272	[]completed/new finding(s)	DIST-0310456 1
3 POLE TRAMP DOUBLE DEAD END	[]pre-existing cond chked	2222 4224 2
!		
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001892	
39.324701000000		
-120.6095360000	/	
010/122B SINGLE WOOD POLE	[] completed/no problems	Total # of Attachments:
42572871	[]completed/new finding(s)	
COUBLE DEAD END	[]pre-existing cond chked	
COORDE DEAD BAIL	1	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39,324682000000		
-120.6095210000		
010/122C SINGLE WOOD FOLE	//completed/no problems	Total # of Attachments:
42572872	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
	Notes: '02 Survey: K002115	
39.324638000000		
-120.6095170000		
010/123 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40809761	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001893	
39.325416000000		
-120.6075070000		
010/124 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments: 1
40878355	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001894	
39.325682000000		
-120.6068280000		
010/125 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
· ·	ſ	
40870149	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K001895	-
39.326089000000		
-120.6058770000		
010/126 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40590179	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
FOOT ONG!		l
	Notes: '02 Survey: K001896	
39.326693000000		
-120.6037900000		

Page 23

POLE High Impact

Inspector Name : RBimSon

Date Inspected : 7-3:13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Detailed Ground Inspections

Desc of Tech ID	Tremostice Trends	
1 1	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed •
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
010/127 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40586198	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	pre-existing cond chked	
FOOT ONLY	I lnot inspetd this patrol	
	Notes: '02 Survey: K001897	<u></u>
39.327203000000	added, az Barvey, kodrójy	
-120.6027500000		
011/128 WDOD POLE STRUCTURE	//lcompleted/no problems	Total # of Attachments: 1
40618840	[]completed/new finding(s)	
2 POLE SUSP		DIST-0310456 1
FOOT ONLY	[]pre-existing cond chked	
FOOT UND	[]not inspetd this patrol	
	Notes: '02 Survey: K001898	
39.328116000000		
-120.6008830000		
011/129 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40586200	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001899	
39.328630000000		
-120.5998270000		
011/130 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40702403		DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	2201 0320430 1
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001900	
39.329016000000	Motes: '02 Sdivey: R001900	
-120.5989760000	C. H. 39'05" VI	0
011/131 WOOD POLE STRUCTURE		EH 75°
40669084	[/completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K001901	
39.329899000000		
-120-5969490000		
011/132 WOOD POLE STRUCTURE	(/completed/no problems	Total # of Attachments: 1
40761545	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K001902	
39.330456000000		
-120.5956650000		
011/133 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
40748235		DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	5151 0510430 1
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001903	
39.330917000000	Mores: -02 Survey: KUU1903	
-120.5945930000		
011/134 WOOD POLE STRUCTURE	// completed, no problems	
40828482		Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspctd this patrol	
	Notes: '02 Survey: K001904	
39.331750000000		
-120.5927000000		

Inspector Name: RBinson

Date Inspected: 7-3i-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	amprocesson Result	
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Noces	
Long:		
011/135 WOOD POLE STRUCTURE	[[completed (== must l ===	Transit and the second
40818179	[/] completed/no problems	Total # of Attachments: 1
3 POLE DOUBLE VERTICAL	[]completed/new finding(s)	DIST-0310456 1
MEDIUM EQP(AERIAL LIFT; LINE TR	[]pre-existing cond chked	
PRODUCE DE CARACIAN DIFT; DINE TR	[]not inspetd this patrol	
39.332584000000	Notes: '02 Survey: K001905	
-120.5907850000		
011/136 WOOD POLE STRUCTURE		
40870452	mpleted/no problems	Total # of Attachments: 1
2 POLE SUSP	ompleted/new finding(s)	DIST-0310456 1
	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	<u> </u>
39.332867000000	Notes: '02 Survey: K001906	
-120.5897340000	G.H. 4409 V	1611
	5. F. 7701 V	[H 60
011/137A SINGLE WOOD POLE 40876971	[/]completed/no problems	Total # of Attachments: 1
3 POLE SINGLE VERTICAL	[]completed/new finding(s)	DIST-0310456 1
FOOT ONLY	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this parrol	
39.33343200000	Notes: '02 Survey: K001907	
-120.5878070000		
011/137B SINGLE WOOD POLE		
42572786	[/]completed/no problems	Total # of Attachments:
ANGLE 0-30 DEGREES	[]completed/new finding(s)	
ANGES 0-30 DEGREES	[]pre-existing cond chked	
	[]not inepctd this patrol	
10 22276500000	Notes: '02 Survey: K002115	
39.333365000000 -120.5877960000		
011/137C SINGLE WOOD POLE		
12572787	Completed/no problems	Total # of Attachments:
ANGLE 0-30 DEGREES	[]completed/new finding(s)	
WODE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
39.333304000000	Notes: '02 Survey: K002115	
.120.5877930000		
)11/138 WDOD POLE STRUCTURE	10.	
10618843	//completed/no problems	Total # of Attachments: 1
POLE DOUBLE VERTICAL		DIST-0310456 1
OOT ONLY	[]pre-existing cond chked	
OUT CHEE	[]not inspetd this patro1	
9.333436000000	Notes: '02 Survey: K001908	
120.5858910000	,	
11/138B SINGLE WOOD POLE	[/] germal at a d /ma mark 7	
1223342		Total # of Attachments:
	3	
	[]pre-existing cond chked	
	[]not inspetd this patrol	
9.333418000000	Notes:	
120.5858850000		
11/138C SINGLE WOOD POLE	//lcompleted/no problems [
1223341	[]completed/new finding(s)	Total # of Attachments:
	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes:	
9.333373000000		
120.5858660000		

Inspector Name : R Bimsol

Date Inspected : 7.31.13

High Impact

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Tibpeccion Result	Attachment Type/Owner Listed
Framing Config		Accacimient Type/Owner Elbood
	h	
Access:	No. ho a	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	1	
012/139 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40603715	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K001909	
39.332959000000		
-120.5838330000		
012/140 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40593971	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	**pre-existing cond chked	
FOOT ONLY	/ [not inspetd this patrol	
	Notes: '02 Survey: K001910	
39.332778000000		
-120.5817570000		
012/141 WOOD POLE STRUCTURE	√] completed/no problems	Total # of Attachments: 1
40660437	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001911	
39.332662000000		
-120.5804680000		
012/142A SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments: 1
40650157	[]completed/new finding(s)	DIST-0310456 1
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001912	
39.332545000000		
-120.5784530000		
012/142B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572788	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.332532000000		
-120.5784400000		
012/142C SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
42572789	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.332512000000		
-120.5784510000		
012/143 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40761547	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: 102 Survey: K001913	
39.332882000000	-	
-120.5766060000	/	
012/144A SINGLE WOOD POLE	//completed/no problems	Total # of Attachments: 1
40752041	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001914	
39.333217000000		7 Y
-120.5746880000		

Inspector Name : RBimsov

Date Inspected : Z*3i-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		1,20,00000
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
012/144B SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
42572790	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
DOUBLE DEAD IND	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	<u> </u>
39.333138000000	Notes: .03 Survey: K003112	
-120.5747650000		
4	-	1
012/144C SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
42572791	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	·
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.333054000000		
-120.5747790000		
012/145 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments: 1
40828504	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
,	Notes: '02 Survey: K001915	
39.332224000000	-	
-120.5735810000		
012/146 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
42572877	[]completed/new finding(s)	•
SUSPENSION (TWR)	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.331636000000	on barrey. Medazza	
-120.5727470000		
012/147A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40809763	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	PT91-03T0439 I
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
MEDICAL EQP (RECIAD DIFF, DINE IR	Notes: '02 Survey: K001916	
39.331098000000	Notes: 102 Sarvey: R001916	
-120.5720060000	C11 22 04"	USW 750
012/147B SINGLE WOOD POLE	TI. JJ U	V (1) //
	/ completed/no problems	Total # of Attachments:
12572873	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.331083000000		
-120.5720730000		
012/147C SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
2572874	[]completed/new finding(s)	
COUBLE DEAD END	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
9.33102400000		
120.5721080000		
12/148 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
0878376	[]completed/new finding(s)	DIST-0310456 1
- POLE DOUBLE VERTICAL	[]pre-existing cond chked	
EDIUM EQP (AERIAL LIFT; LINE TR	[] not inspetd this patrol	
30 5	Notes: '02 Survey: K001917	
9.329885000000	,	
120.5705400000		

Inspector Name: R Bimsol

Date Inspected: 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
012/149 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40862028	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
39.329147000000	Notes: '02 Survey: K001918	
-120.5694650000 NO 150	[/completed/no problems	Total # of Attachments: 1
40603718	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001920	
39.32820000000		
-120.5681530000		
013/152 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
40602616	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001921	
39.32714000000		
-120.5667580000		
013/153A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40682561	[]completed/new finding(s)	DIST-0310456 1
3 POLE SINGLE VERTICAL	pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol Notes: '02 Survey: K001922	
39.326242000000	Moces: .02 Sdrvey: K001922	
-120.5656060000		
013/153B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572792	[]completed/new finding(s)	iotal # of Actachinelics:
ANGLE 0-30 DEGREES	Dipre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.32622000000	_	
-120.5656130000		
013/153C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572794	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
	[]not inspetd this patrol	
30 305144080000	Notes: '02 Survey: K002115	
39.326144000000 -120.5656660000		
013/154 WOOD POLE STRUCTURE	completed/no problems	maked H of The characters and the characters are the characters and the characters are th
40659118	1 - 1	Total # of Attachments: 1 DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	DI21-0210420 T
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001923	
39.325723000000		
-120.5645750000		
013/155 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
40751977		DIST-0310456 1
3 POLE DOUBLE VERTICAL:	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001924	
39.325149000000		
-120.5634940000		

Page 28

Inspector Name : R Bimsor

Date Inspected :

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Equip # Praming Config Access: HOST Tech ID/Equip #: Lat: Long: Completed/no problems			
Framing Config Access: HOST Tech ID/Equip #: Lat: Lat: Lat: Long: 013/156 WODD POLE STRUCTURE 4	Desc of Tech ID	Inspection Result	Attachments #
ACCESS: Lat: LONG: Long: Long: INOTES I Completed/no problems Total # of Attachments: 1 LONG:	Equip #		Attachment Type/Owner Listed
ACCESS: Lat: LONG: Long: Long: INOTES I Completed/no problems Total # of Attachments: 1 LONG:	Framing Config		
HOST Tech ID/Equip #: Lat: Long: 13/156 WOOD POLE STRUCTURE 4			
Lat: Long: Completed/no problems	HOST Tech ID/Equip #:	Notes	
Completed/no problems Total # of Attachments: 1 1 1 1 1 1 1 1 1 1			
1 completed/no problems Canal delay of Attachments: 1			
		[]completed/no problems	Total # of Attachments: 1
2 POLE SUSP FOOT ONLY Notes: '02 Survey: K001925 Notes: '02 Survey: K001926 Notes: '02 Survey: K001927 Notes: '02 Survey: K001928 Notes: '02 Survey: K001929			DIST-0310456 1
	=	More-existing cond chked	
Notes: '02 Survey: K001925 Notes: '02 Survey: K001925 Notes: '02 Survey: K001925 Notes: '02 Survey: K001926 Notes: '02 Survey: K001927 Notes: '02 Survey: K001928 Notes: '02 Survey: K001929 Notes: '02 Sur		I not import this patrol	
39.323915000000 -120.5617650000 1013/157 WOOD FOLE STRUCTURE 40828484 2 POLE SUSP 1 completed/new finding(s) 1013/158 WOOD FOLE STRUCTURE 40818181 2 POLE SUSP 1 completed/new finding(s) 1 pre-existing cond chked 1 completed/new finding(s) 2 POLE SUSP 1 completed/new finding(s) 2 POLE SUSP 2 POLE SUSP 39.321442000000 -120.5580420000 013/159 WOOD FOLE STRUCTURE 40818387 3 POLE DOUBLE VERTICAL FOOT ONLY 39.320210000000 -120.5589930000 013/160 WOOD POLE STRUCTURE 40828319 3 POLE DOUBLE VERTICAL FOOT ONLY 39.320210000000 -120.558930000 013/160 WOOD POLE STRUCTURE 40828319 3 POLE DOUBLE VERTICAL FOOT ONLY 39.319701000000 -120.558931000 013/160 WOOD POLE STRUCTURE 40828319 3 POLE DOUBLE VERTICAL FOOT ONLY 39.319701000000 -120.5558700000 13/160 WOOD POLE STRUCTURE 40828319 3 POLE DOUBLE VERTICAL FOOT ONLY 39.319701000000 -120.5554700000 13/161 WOOD POLE STRUCTURE 40828318 1 completed/new finding(s) 39.319701000000 -120.5554700000 13/161 WOOD POLE STRUCTURE 40828319 1 completed/new finding(s) 408290185	EGGI. ONFA		
-120.5617650000 013/157 WOOD FOLE STRUCTURE 40828494 2 POLE SUSP FOOT ONLY 39.322670000000 -120.5609310000 013/158 WOOD FOLE STRUCTURE 40818181 2 POLE SUSP FOOT ONLY 1 pre-existing cond chked 1 lnot inspect this patrol Notes: '02 Survey: K001926 1 pre-stisting cond chked 1 lnot inspect this patrol Notes: '02 Survey: K001927 39.32144200000 -120.5584420000 -120.5584420000 -120.5584930000 013/159 WOOD FOLE STRUCTURE 40878357 3 POLE DOUBLE VERTICAL FOOT ONLY 1 completed/new finding(s) 1 pre-existing cond chked 1 not inspect this patrol Notes: '02 Survey: K001927 39.320210000000 -120.558930000 013/160 WOOD POLE STRUCTURE 40859319 3 POLE DOUBLE VERTICAL FOOT ONLY 39.319701000000 -120.5584700000 013/160 WOOD POLE STRUCTURE 40859319 3 POLE DOUBLE VERTICAL FOOT ONLY 39.319701000000 -120.55584700000 014/161 WOOD POLE STRUCTURE 40859318 1 completed/new finding(s) 39.319701000000 -120.55554700000 014/161 WOOD POLE STRUCTURE 40859318 1 completed/new finding(s) 1 completed/new finding(s) 3 FOLE DOUBLE VERTICAL FOOT ONLY 39.319701000000 -120.5554700000 014/161 WOOD POLE STRUCTURE 40859318 1 completed/new finding(s) 31 FOLE DOUBLE VERTICAL FOOT ONLY 31 FOLE DOUBLE VERTICAL FOOT ONLY 32 Survey: K001928 33 FOLE DOUBLE VERTICAL FOOT ONLY 34 FOLE DOUBLE VERTICAL FOOT ONLY 35 FOLE DOUBLE VERTICAL FOOT ONLY 36 FOLE DOUBLE VERTICAL FOOT ONLY 37 FOLE DOUBLE VERTICAL FOOT ONLY 38 FOLE DOUBLE VERTICAL FOOT ONLY 39 FOLE DOUBLE VERTICAL FOOT ONLY 30 FOLE DOUBLE VERTICAL FOOT ONLY 31 FOLE DOUBLE VERTICAL FOOT ONLY 31 FOLE DOUBLE VERTICAL FOOT ONLY 32 FOLE DOUBLE VERTICAL FOOT ONLY 33 FOLE DOUBLE VERTICAL FOOT ONLY 34 FOLE DOUBLE VERTICAL FOOT ONLY 55 FOLE DOUBLE VERTICAL FOOT ONLY 57 FOLE DOUBLE VERTICAL FOOT ONLY 58 FOLE DOUBLE VERTICAL FOOT ONLY 59 FOLE DOUBLE VERTICAL FOOT ONLY 50 FOLE DOUBLE VERTIC		Notes: .03 Survey: Kools25	
Ols/157 WOOD POLE STRUCTURE		}	
		1 1 1/2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Imperal # of httachments, 1
			1 "
Inct inspectd this patrol Notes: '02 Survey: K001926			DIST-0310456 1
Notes: '02 Survey: K001926	2 POLE SUSP		
39.322670000000 -120.5600910000 013/158 WOOD FOLE STRUCTURE (00181811	FOOT ONLY		
-120.5600910000 013/158 WOOD FOLE STRUCTURE 40818181 2 FOLE SUSP FOOT ONLY 39.321442000000 -120.5584420000 013/159 WOOD FOLE STRUCTURE 40878357 3 FOLE DOUBLE VERTICAL FOOT ONLY 39.320210000000 -120.5568930000 013/160 WOOD FOLE STRUCTURE 40889319 3 FOLE DOUBLE VERTICAL FOOT ONLY 1 Inot inspect dris patrol Notes: '02 Survey: K001928 39.320210000000 -120.5568930000 013/160 WOOD FOLE STRUCTURE 40889319 3 FOLE DOUBLE VERTICAL FOOT ONLY 1 Inot inspect dris patrol Notes: '02 Survey: K001928 39.320210000000 -120.5568930000 013/160 WOOD FOLE STRUCTURE 4089319 3 FOLE DOUBLE VERTICAL FOOT ONLY 1 Completed/no problems Total # of Attachments: 1		Notes: '02 Survey: K001926	
Completed/no problems Completed/no problems Completed/new finding(s) DIST-0310456 DIST	39.322670000000		
	-120.5600910000		
	013/158 WOOD POLE STRUCTURE		
[] pre-existing cond chked [] Inot inspctd this patrol Notes: '02 Survey: K001927 39.32144200000 -120.5584420000 013/159 WOOD FOLE STRUCTURE [] completed/no problems [] completed/no problems [] completed/no problems [] completed/no problems [] DIST-0310456 1 1	•		DIST-0310456 1
Inct inspetd this patrol Notes: '02 Survey: K001927			
Notes: '02 Survey: K001927	I - · -		
39.32144200000 -120.5584420000 013/159 WOOD POLE STRUCTURE 40878357 3 POLE DOUBLE VERTICAL FOOT ONLY 1 Inot inspect this patrol Notes: '02 Survey: K001928 39.320210000000 -120.5568930000 013/160 WOOD POLE STRUCTURE 40859319 3 POLE DOUBLE VERTICAL FOOT ONLY 1 Completed/no problems	1001 021		
-120.5584420000 013/159 WOOD POLE STRUCTURE 40878357 3 FOLE DOUBLE VERTICAL FOOT ONLY 1 Int inspetd this patrol Notes: '02 Survey: K001928 39.320210000000 -120.5568930000 013/160 WOOD POLE STRUCTURE 40859319 3 POLE DOUBLE VERTICAL FOOT ONLY 1 Completed/no problems Co	22 221442000000		· · · · · · · · · · · · · · · · · · ·
Clompleted/no problems Total # of Attachments: 1			
Completed/new finding(s) DIST-0310456 1		/ learnisted/no problems	Total # of Attachments: 1
Ipre-existing cond chked Inot inspect this patrol	1	(1) completed/no problems	
[] not inspetd this patrol Notes: '02 Survey: K001928 Notes: '03 Survey: K001929 Notes: '04/161 WOOD POLE STRUCTURE Completed/no problems Notes: '05 Survey: K001929 Notes: '05 S			D131-0310430 1
Notes: '02 Survey: K001928	I -		'
39.320210000000 -120.5568930000 013/160 WOOD POLE STRUCTURE 40859319 3 POLE DOUBLE VERTICAL FOOT ONLY 1 Inot inspctd this patrol Notes: '02 Survey: K001929 39.319701000000 -120.5554700000 014/161 WOOD POLE STRUCTURE 40590185 1 Completed/no problems Total # of Attachments: 1	FOOT ONLY	[]not inspetd this patrol	
013/160 WOOD POLE STRUCTURE [] completed/no problems / Total # of Attachments: 1 40859319 [] completed/new finding(s) 3 POLE DOUBLE VERTICAL [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: K001929 39.319701000000 [] Notes: '02 Survey: K001929 39.319701000000 [] Total # of Attachments: 1 40590185 [] completed/new finding(s) DIST-0310456 1		Notes: '02 Survey: R001928	
013/160 WOOD POLE STRUCTURE [] completed/no problems / Total # of Attachments: 1 40859319 [] completed/new finding(s) 3 POLE DOUBLE VERTICAL [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: K001929 39.319701000000 [] Notes: '02 Survey: K001929 39.319701000000 [] Total # of Attachments: 1 40590185 [] completed/new finding(s) DIST-0310456 1	39.320210000000	note Cont	ca 1.186
40859319 [] completed/new finding(s) DIST-0310456 1 3 POLE DOUBLE VERTICAL [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: K001929 39.319701000000			
3 FOLE DOUBLE VERTICAL FOOT ONLY [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: K001929 39.319701000000 -120.5554700000 014/161 WOOD POLE STRUCTURE 40590185 [] completed/no problems 40590185 [] completed/new finding(s) DIST-0310456 1	013/160 WOOD POLE STRUCTURE	[]completed/no problems [
Total # of Attachments: 1 Completed/new finding(s) DIST-0310456 1	40859319	[]completed/new finding(s)	DIST-0310456 1
Notes: '02 Survey: K001929 39.3197010000000 -120.5554700000 014/161 WOOD POLE STRUCTURE (3 POLE DOUBLE VERTICAL		
39.3197010000000 -120.5554700000 014/161 WOOD POLE STRUCTURE (]completed/no problems	FOOT ONLY	[] not inspetd this patrol	
-120.5554700000 014/161 WOOD POLE STRUCTURE (]completed/no problems		Notes: '02 Survey: K001929	
-120.5554700000 014/161 WOOD POLE STRUCTURE (]completed/no problems	39.319701000000		
014/161 WOOD POLE STRUCTURE (completed/no problems Total # of Attachments: 1 40590185 [completed/new finding(s) DIST-0310456 1		1	
40590185 []completed/new finding(s) DIST-0310456 1		[]completed/no problems	Total # of Attachments: 1
1,000	1	1	DIST-0310456 1
	3 POLE OOUBLE VERTICAL	Apre-existing cond chked	
The state of the s			
FOOT ONLY	FOOT UNLI	Notes: 102 Survey: K001931	
		Acces. 02 parvey: Moores	-
39.319303000000			
-120.5548060000 014/162 WOOD FOLE STRUCTURE Clompleted/no problems Total # of Attachments: 1		(1	Total # of Attachments: 1
7.1 2.1 2.4 (m. 61-21-m/m) NTET 02304E6 1			
40574005	1		
2 POLE SUSP []pre-existing cond chked			
FOOT ONLY [] not inspetd this patrol	FOOT ONLY		
Notes: '02 Survey: K001932		Notes: '02 Survey: K001932	i .
39.318827000000	39.318827000000		
-120.5530030000	-120.5530030000		
014/163 WOOD POLE STRUCTURE [] completed/no problems Total # of Attachments: 1	014/163 WOOD POLE STRUCTURE		
40660441 []completed/new finding(s) DIST-0310456 1		[] completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL Vipre-existing cond chked	N Company of the Comp	No pre-existing cond chked	
MEDIUM EOP (AERIAL LIFT; LINE TR) not inspetd this patrol			
Notes: '02 Survey: K001933			
39.318492000000	39.318492000000		
-120.5520950000	•		

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
lat:	1,500	
iong:		
14/164 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
10650158	[]pre-existing cond chked	D151-0510-250 1
POLE SUSP	- · -	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K001934	
39.317982000000		
120.5509930000		Total # of Attachments: 1
14/165A SINGLE WOOD POLE	[]completed/no problems	l ·
10771885	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	Xipre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	Inot inspetd this patrol	
	Notes: '02 Survey: K001935	
39.317250000000		
-120.5492410000	<u> </u>	
014/165B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
12572796	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	Spre-existing cond chked	
	[]not inspetd this patrol	
•	Notes: '02 Survey: K002115	
39.317177000000		
120.5492710000		
14/165C SINGLE WOOD POLE	[]completsd/no problems	Total # of Attachments:
2572797	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	<u> </u>
39.317125000000		
-120.5492930000		
014/166 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40752045	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
WEDIOW EOS (WESTAL PIET, DINE IK	Notes: '02 Survey: K001936	
	Notes: 02 Barvey. Roomson	
39.316835000000		
-120.5474350000	[]completed/no problems	Total # of Attachments: 1
014/167A SINGLE WOOD POLE	[]completed/new finding(s)	"
40821766		D101-0310430 1
3 POLE DOUBLE VERTICAL	fore-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001937	
39.316421000000		
-120_5454960000		Mark - 1 Mark Retainments.
014/167B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572798	[]completed/new finding(s)	
DOUBLE DEAD END	Upre-existing cond chked	
	{] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.31636800000		
-120.5455930000		
114/167C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572799	[completed/new finding(s)	
OOUBLE DEAD END	No pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.316357000000		

Inspector Name : R Simson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		•••
Access:		
HOST Tech ID/Equip #:	Notes	· · · · · · · · · · · · · · · · · · ·
Lat:		
Long:		1
014/168 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40809765	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K002114	
39.315207000000		
-120.5452350000		
014/169A SINGLE WOOD POLE	√l completed/no problems	Total # of Attachments: 1
40878359	[]completed/new finding(s)	DIST-0310456 1
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.314458000000		
-120.5449250000	1	
014/169B SINGLE WOOD POLE	[/]completed/no probleme	Total # of Attachments:
42572802	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.314446000000		
-120.5450090000		
014/169C SINGLE WOOD POLE	[/] completed/no problems	Total # of Attachments:
42572803	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.314407000000		
-120.5450550600	ļ.,	
014/170A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40970151	()completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	ore-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
39.313392000000	Notes: '02 Survey: K002116	
-120.5435880000 014/170B SINGLE WOOD POLE	[]completed/no problems	Total # of Phtachyonta
42572804	[]completed/no problems []completed/new finding(s)	Total # of Attachments:
42572804 ANGLE 0-30 DEGREES	pre-existing cond chked	
ANGUE U-30 DEGREES	1 /	
	{]not inspctd this patrol Notes: '02 Survey: K002115	L
39.313345000000	Mores: -02 Survey: K002115	
-120.5436240000		
-120.5436240000 014/170C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572805	[]completed/new finding(s)	TOCAL # 04 STUDGETTOS:
ANGLE 0-30 DEGREES	Spre-existing cond chked	
PARODA V-3V DEGREES	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.313304000000	acces. oz barvey: Rov2115	
-120.5436490000		
014/171A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
405901 8 8	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002117	
39.313081000000	CH. 30'07" V	/ .A.

Inspector Name: $\frac{RB_{1}MS0N}{7\cdot31\cdot13}$

High Impact

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
	THEFOCULOR REDUZE	Attachment Type/Owner Listed
Equip #		112000000000000000000000000000000000000
Framing Config		
Access:	37 - 1	
HOST Tech ID/Equip #:	Notes	
Lat:		·
Long:		
014/171B SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572806	(completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.313047000000	1	
-120.5415720000	/	
014/171C SINGLE WOOD POLE	[/] completed/no problems	Total # of Attachments:
42572807	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
MACHE 0-30 DEGREES	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	<u> </u>
	Modes: .05 SmineA: Knositz	
39.313005000000		
-120.5415870000		
014/172 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40589136	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K002118	
39.312652000000		
-120.5408170000		
014/173A SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments: 1
40682565	[]completed/new finding(s)	DIST-0310456 1
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
AMODE 0-30 DECREES	[]not inspetd this patrol	
	Notes: '02 Survey: K002119	
30 31162000000	and the same of th	
39.311578000000		
-120.5384710000	[/completed/no problems	Total # of Attachments:
014/173B SINGLE WOOD POLE	•	
42572808	(completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.311529000000		
-120.5384610000		
014/173C SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572809	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.311487000000		
-120.5384990000		
014/174 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	
40669087	[]pre-existing cond chked	
	_	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002120	
39.311010000000		
-120.5380700000		Maria II and Baka abasanta. 1
015/175 WOOD POLE STRUCTURE	[/completed/no problems	Total # or Attachments: 1
40590191	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002121	
39.310433000000		
-120.5376240000		

Page 32

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Inspector Name: RBMSoN Date Inspected: 7-31-13

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
	Indposition and and	Attachment Type/Owner Listed
Equip #		1
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
015/176 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40586201	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
TOOT OND!	Notes: '02 Survey: K002122	
39,309808000000		1 - 1 - 1 - 1
	CH. 32 02	TED 60
-120.5371860000 015/177 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	
40660445	[]pre-existing cond chked	,
3 POLE DOUBLE VERTICAL		
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002123	
39.308755000000		
-120.5359620000		
015/178A SINGLE WOOD POLE	//completed/no problems	Total # of Attachments: 1
40650161	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
1001 5.121	Notes: '02 Survey: K002124	
70 700705000000		
39.308305000000		
-120.5353820000	[]completed/no problems	Total # of Attachments:
015/178B SINGLE WOOD POLE	1 1	
42572810	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.308299000000		
-120.5354240000		
015/178C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572811	Micompleted/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
ARGHE 0-30 BEGREEO	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.308211000000	Sait TOP	
-120.5354270000	1, -1	Total # of Attachments: 1
015/179 WOOD POLE STRUCTURE	[/]completed/no problems	
40751979	[]completed/new finding(s)	DT010310430 T
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[] not inspctd this patrol	
	Notes: '02 Survey: K002125	
39.307994000000		
-120.5337100000		
015/180 LATTICE STEEL TOWER	[/]completed/no problems	Total # of Attachments:
40755599	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
1001 01121	Notes: '02 Survey: K002120	
20 207621000000		
39.307621000000		
-120.5316800000		Total # of Attachments: 1
015/181 WOOD POLE STRUCTURE	[]completed/new finding(s)	
40819930	[]completed/new rinding(s.	
3 POLE DOUBLE VERTICAL		
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspctd this patrol	
	Notes: '02 Survey: K00212	
39.307305000000	1	
-120 5296730000		

Page 33

Inspector Name : R B; MSON Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	/	
015/182 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40809767	[]completed/new finding(s)	DIST-0310456 1
3 POLE OCUBLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT;LINE TR	[]not inspetd this patrol Notes: '02 Survey: K002128	
39.307139000000		
-120.5281190000	C.H. 36 03"	VEH 75°
015/183 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments: 1
40862280	[]completed/new finding(s)	DIST-0310456 1
		D1S1-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	<u> </u>
	Notes: '02 Survey: K002129	
39.307066000000		
-120.5273820000		
015/184A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40862030	[]completed/new finding(s)	DIST-0310456 1
3 POLE SINGLE VERTICAL	Supre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002130	
39.307076000000	_	
-120.5256240000		
015/184B SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572813	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked	
ANGEL G-GG DEGICES	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
38 20004000000	Notes: '02 Survey: R002115	
39.307049000000		
-120.5256070000		
015/184C SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
42572814	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	pre-existing cond chked]
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.306983000000		
-120.5256100000		
015/185 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40608754	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	Mpre-existing cond chked	
FOOT ONLY	pre-existing cond chked []not inspctd this patrol	
	Notes: '02 Survey: K002131	
39.307218000000		
-120.5249570000		
015/186A SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40586203	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	More-existing cond chked	PIDI OPIGEO I
FOOT ONLY	I not inspetd this patrol	
SOOT ONDI		
20. 20760600000	Notes: '02 Survey: K002132	
39.307606000000	1	
-120.5237320000		
015/186B SINGLE WOOD POLE	[J]completed/no problems	Total # of Attachments:
42572815	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: K002115	<u> </u>
39.30757000000		

Inspector Name : RBinson

Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
	Notes	
HOST Tech ID/Equip #:	Moces	
Lat:		
Long:		
15/186C SINGLE WOOD POLE	[/] completed/no problems	Total # of Attachments:
2572816	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.30755500000	Nesser se	
120.5236690000	[]completed/no problems	Total # of Attachments: 1
15/187 WOOD POLE STRUCTURE		l control of the cont
10702427	[]completed/new finding(s)	DISI-0310436 1
POLE SUSP	pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002133	
39.308739000000		
-120.5222400000		
16/188 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
10590194	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
	[] not inspetd this patrol	
FOOT ONLY	Notes: '02 Survey: K002134	
	Notes: '02 Survey: K002134	
39.309528000000		
-120.5211260000		
018/189A SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
10594584	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K002135	
39.309907000000		
-120.5207870000	^	
016/189B SINGLE WOOD POLE	// lcompleted/no problems	Total # of Attachments:
	[]completed/new finding(s)	
42572817	[]pre-existing cond chked	
ANGLE 0-30 DÉGREES	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.30989 70 00000		
-120.5207200000		
016/189C SINGLE WOOD POLE	[/]completed/no problems	Total # of Attachments:
42572 818	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
20 20021000000		
39.3098310000 0 0 -120.5206820000		
	[]completed/no problems	Total # of Attachments:
016/190 WOOD POLE STRUCTURE	J compreted/no problems	" "
40660449	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K002136	
39.310513000000		
-120.5204330000		
016/191 WOOD POLE STRUCTURE	[/]completed/nc problems	Total # of Attachments:
40650162	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
	[]not inspetd this patrol	
FOOT ONLY		
FOOT ONLY 39.311527000000	Notes: '02 Survey: K00213	

Inspector Name: RBimson

Date Inspected: 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

	Poguit	Attachments #
Desc of Tech ID	Inspection Result	Attachment Type/Owner Listed
Equip #		Accadement Type/owner history
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		[
016/192A SINGLE WOOD POLE	(/completed/no problems	Total # of Attachments:
40751981	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	<u></u>
	Notes: '02 Survey: K002138	
39.3129100000 00		
-120.5192660000		
016/192B SINGLE WOOD POLE	[Acompleted/no problems	Total # of Attachments:
42572820	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.312899000000		
-120.5192090000	[/]completed/no problems	
016/192C SINGLE WOOD POLE	[completed/no problems	Total # of Attachments:
42572821	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspctd this patrol	
	Notes: '02 Survey: K002115	5
39.312851000000		
-120.5191580000	/	
016/193 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40755601	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K00213	
39.313781000000		
-120.5178670000		
016/194A SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
40822544	[]completed/new finding(s) I
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	I I
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K00214	
39.314807000000		
-120.5164830000		
016/194B SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572822	[]completed/new finding(s	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K00211	5
39.314778000000		
-120.5164860000		
016/194C SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572823	[]completed/new finding(s	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K00211	3
39.314783000000		
-120.5164810000	I A service of the problems	Total # of Attachments:
016/195A SINGLE WOOD POLE	[/completed/no problems []completed/new finding(s	
40818747		
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K00214	
39.315099000000		
-120.5141380000		

Inspector Name : RBimso~

Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		- 12 - 12 - 12 - 12 - 12 - 12 - 12 - 12
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
016/195B SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572824	[] completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.315058000000	Moces: .03 Survey: K005112	
-120.5141410000		
016/195C SINGLE WOOD POLE	Ficompleted/no problems	
		Total # of Attachments:
42572825	[]completed/new finding(s)	·
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.315014000000		
120.5141370000		
016/196 WOOD POLE STRUCTURE	¿ completed/no problems	Total # of Attachments:
10862282	[]completed/new finding(s)	
POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K002142	
9.314605000000		
120.5110900000		
16/197 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
0856571	[]completed/new finding(s)	DIST-0310456 1
POLE DOUBLE VERTICAL	[]pre-existing cond chked	
OOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K002143	
9.314184000000		
120.5088250000		
16/198 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
0590198	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	Mpre-existing cond chked	1 101-0310436 L
EDIUM EQP(AERIAL LIFT: LINE TR	Inot inspetd this patrol	
22401. Set famend Dirt, ding in	Notes: '02 Survey: K002144	
9.314110000000	Notes: 02 Survey: K002144	
120.5076010000		
16/199 WOOD POLE STRUCTURE	[/completed/no problems	
0586204		Total # of Attachments: 1
		DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
IGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002145	
9.31395900000		
120.5058950000		
17/200 WOOD POLE STRUCTURE	[/] completed/no problems	Total # of Attachments: 1
0618887	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
GHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002146	
3.313902000000		
.20.5047030000		
7/201A SINGLE WOOD POLE	[] completed/no problems	Total # of Attachments: 1
586206	[]completed/new finding(s)	DIST-0310456 1
POLE SINGLE VERTICAL	[]pre-existing cond chked	
GHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002147	
3.313833000000	8 0-	7ED 65°
.5450550000	10 · 2	

Page 37

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name: R Bimson

Date Inspected: 7-31-13

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
017/201B SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
42572826	Completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
ANGUE 0-30 DEGREES	()not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.313781000000	I WENN MENN	Avcore
-120.5027960000		Total # of Attachments:
017/201C SINGLE WOOD POLE		TOTAL # OF ACCACHIGERES:
42572827	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.313720000000		
1		
-120.5027940000	[] completed/no problems	Total # of Attachments: 1
017/202 WOOD POLE STRUCTURE	[]completed/new finding(s)	
40560454		320. 0320.37 -
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002148	
39.313975000000		
-120.5012080000		
017/203 WOOD POLE STRUCTURE	(] completed/no problems	Total # of Attachments: 1
40653621	[]completed/new finding(s)	DIST-0310456 1
	[]pre-existing cond chked	
2 POLE SUSP	[]not inspetd this patrol	
LIGHT EQP (CREW CABS, PICKUPS)	Notes: '02 Survey: K002149	
	Notes: 702 Burvey: Kovales	
39.314153000000		
-120.4998640000		los a 2 n of 2 the characters 2
017/204 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments: 1
40762144	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K002150	
39.314242000000		
1		
-120.4989720000	[.]completed/no problems	Total # of Attachments: 1
017/205 WOOD POLE STRUCTURE	[]completed/new finding(s)	
40752047		
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K00215	1
39.314432000000	1011 52 27	n hand it. It was to
-120.4977370000	OB 30 0/	Ver 67
017/206 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
40810274	[]completed/new finding(s	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
DIGHT BUT (CREW CARD) FICKOFS)	Notes: '02 Survey: K00215	
39.314605000000	K	
-120.4964630000	1000	Total # of Attachments: 1
017/207 WOOD POLE STRUCTURE	Completed/no problems	
40809769	completed/new finding(s) DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K00215	3
39.314798000000	011	
-120.4950780000	Broken Insul	stt

Page 38

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name: R BinsenDate Inspected: 7-31-13

High Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
017/208 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
41120242	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002154	
39.314983000000		
-120.4935040000		
017/209 WOOD POLE STRUCTURE	[completed/no problems	Total # of Attachments: 1
41120243	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002155	
39.315088000000		
-120.4924680000		
017/210 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments: 1
40618890	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspctd this patrol	
	Notes: '02 Survey: K002156	
39.315545000000	last with the	1 B
-120.4909810000	C. H. 40 02	VEH 70°
017/211 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments: 1
40586207	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001939	
39.315896000000		
-120.4898270000		
017/212 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40660458	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K001940	
39.316228000000		
-120.4884270000	/	
018/213 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments: 1
40590200	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001941	
39.316 6 38000000		
-120.4857680000		
018/214 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
40589137	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001942	
39.317056000000	111 211 112	1-11 - 6
-120.4836720000	CUT 37 01	VETY 10
018/215 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
40682569	[]completed/new finding(s)	DIST-0310456 1
ANGLE 0~30 DEGREES	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001943	
39.317210000000		
-120.4828340000		

Inspector Name : RBinson

Date Inspected : 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
raming Config		
Access:		
Rocess: NOST Tech ID/Equip #:	Notes	
	NOCEB	
Lat:		
long:	1.7	
18/216 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
0650165	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
TOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001944	
39.317304000000		
120.4819600000		
18/217 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
0751983	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
TOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001945	
9.31745200000		7 = - 0
-120.4807290000	64 38 03	· `PED '70
18/218 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
0755603	[]completed/new finding(s)	
=	** Ipre-existing cond chked	
POLE SUSP	not inspetd this patrol	
FOOT ONLY	Notes: '02 Survey: K001946	
	Mores: 'UZ Survey: Kuul946	
9.31759000000		
120.4791120000		Imple 2 in a 2 throughoute 2
18/219 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
10810276	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	<u> </u>
	Notes: '02 Survey: K001947	
39.317765000000	10:1 70/2/	1151 17.0
-120.4773540000	1-H. 30 05	VET 10
18/220 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
10821579	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	Thre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR) not inspetd this patrol	
	Notes: '02 Survey: K001948	
39.317953000000		
-120.4758210000		
018/221 WOOD POLE STRUCTURE	(]completed/no problems	Total # of Attachments: 1
10865429	[]completed/new finding(s)	The state of the s
	Store-existing cond chked	
POLE SUSP	[not inspetd this patrol	
FOOT ONLY	Notes: '02 Survey: K001949	
	Modes: -02 Survey: A001949	•
39.31813700000	11 27 AK	VEH 70°
-120.4737960000	CH 3/ 00	
18/222 WOOD POLE STRUCTURE	[completed/no problems	Total # of Attachments: 1
0862032	[]completed/new finding(s)	DIST-0310456 1
POLE COUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001950	
39.318193000000		
-120.4729540000		
18/223 WOOD POLE STRUCTURE	[/] completed/no problems	Total # of Attachments: 1
40590203	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
	[]not inspetd this patrol	
COI ONLI		
FOOT ONLY	Notes: 02 Survey: K001951	
39.318621 0 00000		

1ge 40

nct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

der : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name : <u>R Bimsen</u>

Date Inspected : <u>7-31-3</u>

High Impact

esc of Tech ID	Inspection Result	Attachments #
quip #		Attachment Type/Owner Listed
raming Config		
cess:		
ST Tech ID/Equip #:	Notes	
at:		
ong:		
9/224 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments: 1
590206	[]completed/new finding(s)	
	[]pre-existing cond chked	
POLE TRAMP DOUBLE DEAD END	[] not inspetd this patrol	
GHT EQP (CREW CABS, PICKUPS)		
	Notes: '02 Survey: K001952	
.319171000000	1	
20.4683180000		1 1 2 H C 214 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
9/225A SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
586209	[] completed/new finding(s)	DIST-0310456 1
POLE SINGLE VERTICAL	[]pre-existing cond chked	
GHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K001953	
.319406000000		
20.4674730000		
9/225B SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
572828	[]completed/new finding(s)	
GLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
.319339000000	100001 02 Dalvey! News-	
20.4674300000	//completed/no problems	Total # of Attachments:
9/225C SINGLE WOOD POLE	7 7 7	
572829	[]completed/new finding(s)	
GLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
.319256000000		
20.4674310000		
9/226 WOOD POLE STRUCTURE	[/] completed/no problems	Total # of Attachments: 1
668903	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
GHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K001954	
.319355000000	Che all in	
20.4664630000	CH 77 11	VEH 66°
9/227 WOOD POLE STRUCTURE	[completed/no problems	Total # of Attachments: 1
659726	[]completed/new finding(s)	DIST-0310456 1
	[]completed/new finding(s) []pre-existing cond chked	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked []not inspctd this patrol	
POLE SUSP GHT EQP (CREW CABS, FICKUPS)	[]pre-existing cond chked	
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000	[]pre-existing cond chked []not inspctd this patrol	
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955	
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE	[]pre-existing cond chked []not inspetd this patrol Notes: '02 Survey: K001955	Total # of Attachments: 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985	[]pre-existing cond chked []not inspetd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s)	Total # of Attachments: 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP	[]pre-existing cond chked []not inspetd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked	Total # of Attachments: 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD FOLE STRUCTURE 751985 POLE SUSP	[]pre-existing cond chked []not inspetd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD FOLE STRUCTURE 751985 POLE SUSP DIUM EQP(AERIAL LIFT; LINE TR	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD FOLE STRUCTURE 751985 POLE SUSP DIUM EQP (AERIAL LIFT; LINE TR	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001956	Total # of Attachments: 1 DIST-0310456 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP DIUM EQP (AERIAL LIFT; LINE TR .319329000000 20.4640470000	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001956	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP DIUM EQP (AERIAL LIFT; LINE TR .319329000000 20.4640470000 9/229 WOOD POLE STRUCTURE	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001956 []completed/no problems []completed/new finding(s)	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP DIUM EQP (AERIAL LIFT; LINE TR .319329000000 20.4640470000 9/229 WOOD POLE STRUCTURE 771072	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001956	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP DIUM EQP (AERIAL LIFT; LINE TR .319329000000 20.4640470000 9/229 WOOD POLE STRUCTURE 771072 POLE SUSP	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001956 []completed/no problems []completed/new finding(s)	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP DIUM EQP (AERIAL LIFT; LINE TR .319329000000 20.4640470000 9/229 WOOD POLE STRUCTURE 771072	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001956 []completed/no problems []completed/new finding(s) []pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
POLE SUSP GHT EQP (CREW CABS, PICKUPS) .319360000000 20.4652200000 9/228 WOOD POLE STRUCTURE 751985 POLE SUSP EDIUM EQP (AERIAL LIFT; LINE TR .319329000000 20.4640470000 9/229 WOOD POLE STRUCTURE 771072 POLE SUSP	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001955 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: K001956 []completed/new finding(s) []pre-existing cond chked []pre-existing cond chked []not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1

Inspector Name : R Bimson

Date Inspected : 7-31-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		2, 50, 0, 110, 110, 110, 110, 110, 110, 1
Access:		
HOST Tech ID/Equip #:	Notes	<u></u>
Lat:	110000	
Long:		
019/230 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments: 1
40819360	[]completed/new finding(s)	DIST-0310456 1.
2 POLE SUSP	Pre-existing cond chked	
MEDIUM EOP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
Minister Par (smitting pri 1) area in	Notes: '02 Survey: K001958	
39,3191950000 00	3.04021	
-120.4605400000		
019/231 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
40826541	[]completed/new finding(s)	DIST-0310456 1
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001959	
39.319151000000	12 1 1	- E
-120,4591660000	16H. 33 OL	PED 55°
019/232 WOOD POLE STRUCTURE	[Completed/no problems	Total # of Attachments: 1
40870454]completed/new finding(s)	i i i i i i i i i i i i i i i i i i i
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K001960	
39.318912000000		
-120.4579500000		
019/233 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
40862034	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspctd this patrol	
	Notes: '02 Survey: K001961	
39.318687000000		
-120.4567170000		
019/234 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments: 1
40590209	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K001962	
39.318486000000	2 16 1161 .7	VEH 55
-120.4555920000	CH. 770/	
019/235 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
40602593	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
	Notes: '02 Survey: K001963	
39.318307000000		
-120.4545650000		
019/236 WOOD POLE STRUCTURE	(completed/no problems	Total # of Attachments: 1
40702429	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K001964	
39.318263000000		
-120.4533860000	Plcompleted/no problems	Total # of Attachments: 1
019/237 WOOD POLE STRUCTURE	[]completed/new finding(s)	
40669088	[]pre-existing cond chked	220-30 1
2 POLE SUSP	[]not inspetd this patrol	
MEDIUM EQP(AERIAL LIFT;LINE TR	Notes: '02 Survey: K001965	
30 31905300000	2.0000. 02 Dar vey, 1001763	
39.318053000000 -120.4513380000		
-750.431330000		

Inspector Name : RB\Mson

Date Inspected : Y-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config	1	-15-14 mind minde
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
020/238 WOOD POLE STRUCTURE	[_completed/no problems	Total # of Attachments: 1
40590212	[]completed/new finding(s)	DIST-0310456 1
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K001966	
39.31792800000		
-120.4494320000		
020/239A SINGLE WOOD POLE	(/completed/no problems	Total # of Attachments: 1
40597041	[]completed/new finding(s)	DIST-0310456 1
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
0 3103556666	Notes: '02 Survey: K001967	
39.317905000000 -120.4480680000		
120/239B SINGLE WOOD POLE	6.1	
120/2398 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
NGLE 0-30 DEGREES	[]completed/new finding(s)	
NGME 0-30 DEGREES	pre-existing cond chked	
	(]not inspetd this patrol	
9.317827000000	Notes: '02 Survey: K002115	
120.4480340000		
20/239C SINGLE WOOD POLE		
2572831	[]completed/no problems	Total # of Attachments:
NGLE 0-30 DEGREES	[]completed/new finding(s)	
NODE 0-00 DEGREES	typre-existing cond chked	
	Notes: '02 Survey: K002115	
9.317804000000	Notes: '02 Survey: K002115	
120.4480400000		
20/240 WOOD POLE STRUCTURE	Completed/no problems	The state of the s
0660462		Total # of Attachments: 1
POLE SUSP	[] pre-existing cond chked	DIST-0310456 1
OOT ONLY	I Inot inspetd this patrol	
	Notes: '02 Survey: K001968	
9.318312000000		
120.4463670000	CH. 49 34	UEH 70
0/241 WOOD POLE STRUCTURE		Total # of Attachments: 1
0669062	[]completed/new finding(s)	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
OOT ONLY	[]not inspetd this patrol	
	Notes: 102 Survey: K001969	
.318578000000		
20.4453360000		
0/242 WOOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments: 1
751987	1.	DIST-0310456 1
POLE SUSP	[]pre-existing cond chked	
OT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001970	
.319227000000		
20.4432580000		
0/243A SINGLE WOOD POLE	[]completed/no problems	Total # or Attachments: 1
761259	[]completed/new finding(s)	DIST-0310456 1
POLE SINGLE VERTICAL	[]pre-existing cond chked	
DIUM EQP(AERIAL LIFT;LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K001971	
.319836000000		
20.4413110000		

Inspector Name: RBINGON

Date Inspected: 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	110000	
Long:		
020/243B SINGLE WOOD POLE	[completed/no problems	Total # of Attachments:
42572832	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
ZMOZE V-30 PEOMEED	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	<u> </u>
39.319820000000		
-120.4412690000		
020/243C SINGLE WOOD POLE	[ccmpleted/no problems	Total # of Attachments:
42572833	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	(Inot inspetd this patrol	
	Notes: '02 Survey: K002115	
39.319841000000		•
-120.4412340000		
020/244 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40828486	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: K001972	<u> </u>
39.320737000000	1 211	
-120.4401070000	1 CH. 40 0	70 VEH 70°
020/245 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40826543	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K001973	
39.321754000000		
-120.4388550000		
020/246 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40878374	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001974	
39.322807000000		
-120.4376720000		
020/247A SINGLE WOOD POLE	[completed/no problems	Total # of Attachments:
40862036	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001975	
39.323665000000		
-120.4366650000		,
020/247B SINGLE WOOD POLE	[/completed/no problems	Total # of Attachments:
42572835	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.323602000000	/	
-120.4366610000		Total # of Attachments:
020/247C SINGLE WOOD POLE	[]completed/no problems []completed/new finding(s)	Total # Of Attachments:
42572836 ANGLE 0-30 DEGREES	[]pre-existing cond chked	
MYGDE V-3V DEGREES	[] not inspetd this patrol	
	I INOL INSUCCO THIS DECIOL	
39.323561000000	Notes: '02 Survey: K002115	

Inspector Name: KBimson

Date Inspected: 7-31-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	THE RESULT	Attachment Type/Owner Listed
Framing Config		accediment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	110000	
Long:		
020/248 WOOD POLE STRUCTURE	L-scompleted/no problems	Total # of Attachments:
40590215	[]completed/new finding(s)	Total # Of Accaciments:
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001976	<u> </u>
39.324032000000	1	
-120.4354710000	,	
021/249 WOOD POLE STRUCTURE	[.]completed/no problems	Total # of Attachments:
40595354	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001977	<u></u>
39.324507000000	_	
-120.4340160000		
021/250 WOOD POLE STRUCTURE	//lcompleted/no problems	Total # of Attachments:
40594585	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001978	
39.324911000000		
-120.4324470000		
021/251 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40650466	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspotd this patrol	
	Notes: '02 Survey: K001979	
39.325610000000		
-120.4308660000		
021/252 WOOD FOLE STRUCTURE		Total # of Attachments:
40545420	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
TA DOCORGO	Notes: '02 Survey: K001980	
39.326202000000		
-120.4292040000		
021/253 WOOD POLE STRUCTURE 40755702		Total # of Attachments:
2 POLE SUSP	[]completed/new finding(s)	
	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
39.326579000000	Notes: '02 Survey: K001981	
-120.4281480000		
021/254 WOOD POLE STRUCTURE	[] gownloted/y=	
10752048	[]completed/no problems []completed/new finding(s)	Total # of Attachments:
POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
-	Notes: '02 Survey: K001982	
9.327265000000	Darvey: KUU1982	
120.4261590000		
21/255 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attach
.0828488	[]completed/new finding(s)	Total # of Attachments:
POLE SUSP	[]pre-existing cond chked	
OOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K001983	
9.327411000000		
120.4246170000]
· · · · · · · · · · · · · · · · · · ·	!	

: 41815880

Page 44

Order

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Inspector Name :__

Date Inspected: ____

Detailed Ground Inspections

Desc of Tech ID Inspection Result Attachments # Equip # Attachment Type/Owner Listed Framing Config Access: HOST Tech ID/Equip #: Notes Lat: Long: 020/248 WOOD POLE STRUCTURE []completed/no problems Total # of Attachments: 40590215 []completed/new finding(s) 2 POLE SUSP []pre-existing cond chked FOOT ONLY []not inspctd this patrol Notes: '02 Survey: K001976 39.324032000000 -120.4354710000 021/249 WOOD POLE STRUCTURE []completed/no problems Total # of Attachments: 40595354 []completed/new finding(s) 2 POLE SUSP []pre-existing cond chked FOOT ONLY []not inspctd this patrol Notes: '02 Survey: K001977 39.324507000000 -120.4340160000 021/250 WOOD POLE STRUCTURE []completed/no problems Total # of Attachments: 40594585 []completed/new finding(s) 2 POLE SUSP []pre-existing cond chked MEDIUM EQP(AERIAL LIFT; LINE TR []mot inspctd this patrol Notes: '02 Survey: K001978 39.324911000000 -120.43244700**0**0 021/251 WOOD POLE STRUCTURE []completed/no problems Total # of Attachments: 40550466 []completed/new finding(s) 2 POLE SUSP []pre-existing cond chked FOOT ONLY []not inspetd this patrol Notes: '02 Survey: K001979 39.325610000000 -120.4308660000 021/252 WOOD POLE STRUCTURE []completed/no problems Total # of Attachments: 40646420 []completed/new finding(s) 2 POLE SUSP []pre-existing cond chked FOOT ONLY []not inspetd this patrol Notes: '02 Survey: K001980 39.326202000000 -120.4292040000 021/253 WOOD POLE STRUCTURE []completed/no problems Total # of Attachments: 40755702 []completed/new finding(s) 2 POLE SUSP []pre-existing cond chked FOOT ONLY []not inspetd this patrol Notes: '02 Survey: K001981 39.326579000000 -120.4281480000 021/254 WOOD POLE STRUCTURE Total # of Attachments: []completed/new finding(s) 40752048 3 POLE DOUBLE VERTICAL []pre-existing cond chked FOOT ONLY []not inspetd this patrol Notes: '02 Survey: K001982 39.327265000000 -120.4261590000 completed/no problems 021/255 WOOD POLE STRUCTURE Total # of Attachments: 40828488 []completed/new finding(s) 2 POLE SUSP []pre-existing cond chked FOOT ONLY []not inspetd this patrol Notes: '02 Survey: K001983 39.327411000000 -120.4246170000

Page 45

Inspector Name :____ Date Inspected : ____

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

High Impact

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
	THEFECTION RESULE.	Attachment Type/Owner Listed
Equip #		Accadiment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
021/256 WOOD POLE STRUCTURE	/ completed/no problems	Total # of Attachments:
4082656 5	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	1
FOOT ONLY	[]not inspetd this patrol	41 @ 93
TOOL ONE	Notes: 102 Survey: K001984	
20 20002500000	Motes: -02 Survey: Kodioa4	
39.327736000000		
-120.4225950000		
021/257 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40878362	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	31 @ 92
	[]not inspetd this patrol	21' (12) 0/2
FOOT ONLY		
	Notes: '02 Survey: K001985	
39.327860000000		4.6 _{4.0}
-120.4213970000		
021/258 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40859321	[]completed/new finding(s)	'iţ.
The state of the s	[]pre-existing cond chked	1000
2 POLE SUSP	1	32 @ 92
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	· De le
	Notes: '02 Survey: K001986	
39.328071000000		
-120.4191550000		
021/259 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
1	[]completed/new finding(s)	
40603721		
2 POLE SUSP	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K001987	
39.328357000000		·
-120.4173740000		
021/260 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
·	1 completed/new finding(s)	source if an instructional
40602619		
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspetd this patrol	
	Notes: '02 Survey: K001988	
39.328304000000		
-120.4168280000		
022/261 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
•		TOTAL W OF APPACIAMENTS.
40603723	[]completed/new finding(s)	•
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K001990	
39.328416000000		
-120.4159320000		
	[]completed/no problems	Total # of Attachments:
022/262 WOOD POLE STRUCTURE		IOCAL & OL MCLACIMICHOS:
40593972	[]completed/new finding(s)	
2 POLE SUSP `	[]pre-existing cond chked	
LIGHT EQP (CREW CABS, PICKUPS)	[]not inspctd this patrol	
	Notes: '02 Survey: K001991	
39.328448000000		
-120.4138320000		
		Total # of Attachments:
022/263 WOOD POLE STRUCTURE]completed/no problems	TOTAL # OF ACCAMINENCE:
40702405	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001992	· · · · · · · · · · · · · · · · · · ·
39.328532000000	_	
-120.4116880000		
~~~. ITT0000000	1	

Inspector Name: SEARCO
Date Inspected: 7-19-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	<b>!</b>	
Long:		
022/264 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40669091	[ ]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K001993	
39.328537000000		
-120.4100690000		<u>, , , , , , , , , , , , , , , , , , , </u>
022/265 WOOD POLE STRUCTURE	√1 completed/no problems	Tota1 # of Attachments:
40 <b>7</b> 71887	[ ]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	100 250
MEDIUM EOP(AERIAL LIFT; LINE TR	( ) not inspetd this patrol	60 @ 95
	Notes: '02 Survey: K001994	
39.328664000000		
-120.4081960000		
022/266 WOOD POLE STRUCTURE		Total # of Attachments:
40771052	completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ] not inspetd this patrol	
	Notes: '02 Survey: K001995	
39.328670000000		
-120.4061400000		
022/267 WOOD POLE STRUCTURE	]completed/no problems	Total # of Attachments:
40810278	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	41 @ 93
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	7/ 6 70
	Notes: '02 Survey: K001996	
39.328793000000		
-120.4041540000		
022/268 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40826547	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	46 @ 930
FOOT ONLY	[]not inspetd this patrol	40 ( 10
	Notes: '02 Survey: K001997	<b>'</b>
39.328815000000		
-120.4021300000	/	
022/269 WOOD POLE STRUCTURE		Total # of Attachments:
40870456	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	71 (m) M2
MEDIUM EQP(AERIAL LIFT; LINE TR	[ lnot inspetd this patrol	36 @ 93
	Notes: '02 Survey: K001998	·
39.328882000000		
-120.4005200000		
022/270 WOOD POLE STRUCTURE	]completed/no problems	Total # of Attachments:
40876973	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K001999	
39.328958000000		· ·
-120.3990860000		
023/271 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40618852	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol Notes: '02 Survey: K002003	
	Distance IDS Survey: KUD20U3	
	Moces: 02 barvey. Moces	
39.328944000000	Motes: 02 barvey: Modes	

Page 47

Inspector Name : BEARD Date Inspected: 7-19-13

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	, , , , , , , , , , , , , , , , , , ,	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	110000	
Long:		
023/272 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40602594	]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspctd this patrol	4/1 @ 930
MEDIUM EQF (MERIAL EIFT, MAND IN	Notes: '02 Survey: K002002	
39.329022000000	itaces, or period.	ı
-120.3964810000		
023/273 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40681169	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
FOOT ONLY	{ Inot inspetd this patrol	3,00 93
FOOT ONLI	Notes: '02 Survey: K002003	
39.329060000000		
-120.3950510000		
023/274 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments:
1	[]completed/new finding(s)	
40669064 3 POLE TRAMP DOUBLE DEAD END	[]pre-existing cond chked	
3 POLE TRAMP DOUBLE DEAD END	[] not inspetd this patrol	
	Notes: '02 Survey: K002004	
	NOCES! 102 Salvey: Nocest	
39.329130000000		
-120.3939570000	Completed/no problems	Total # of Attachments:
023/275 WOOD POLE STRUCTURE	[]completed/new finding(s)	
40751989	[]pre-existing cond chked	
2 POLE SUSP	_	37 6 930
FOOT ONLY	[ ]not inspetd this patrol Notes: '02 Survey: K002005	
	Mofea: .05 anticel: voosoos	
39.329125000000 ,		
-120,3924120000	1/2	Total # of Attachments: 1
023/276 WOOD POLE STRUCTURE	] completed/no problems	
40761261	[]completed/new finding(s)	DIS1*0310456 1
2 POLE SUSP	[]pre-existing cond chked	(# (B) -93
FOOT ONLY	[ ]not inspctd this patrol Notes: '02 Survey: K002006	0, (6-7)
	Notes: '02 Survey: R002006	
39.329166000000		
-120.3907760000	completed/no problems	Total # of Attachments:
023/277A SINGLE WOOD POLE		"
40819362	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[]not inspetd this patrol	
•	Notes: '02 Survey: K002007	
39.329291000000		
-120.3899530000	100000000000000000000000000000000000000	Total # of Attachments:
023/277B SINGLE WOOD POLE		
42572838	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.329266000000		
-120.3899760000		Total i of Attachments.
023/277C SINGLE WOOD POLE		Total # of Attachments:
42572839	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	412' (2) 2.2
	[]not inspetd this patrol	43' @ 43
	Notes: '02 Survey: K002115	
39.329213000000		
_32D 389974DDDD		

Inspector Name : SEARL

Date Inspected : 7-19-13

· High Impact

Funct Loc: Eft.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2 Detailed Ground Inspections

Desc of Tech ID  Equip # Attachment Type/Owner Listed  Framing Config Access: HOST Tech ID/Equip #: Lat: Long:  023/278 WOOD POLE STRUCTURE 40826545 2 POLE SUSP FOOT ONLY  1	·
Framing Config Access: HOST Tech ID/Equip #: Lat: Long: 03/378 WOOD FOLE STRUCTURE 40826545 2 POLE SUSP FOOT ONLY 39.328800000000 -120.3884840000 023/280 WOOD POLE STRUCTURE 40618849 3 POLE SINGLE VERTICAL 5   Open Pole STRUCTURE 6   Open Pole STRUCTURE 7   Open Pole STRUCTURE 7   Open Pole STRUCTURE 8   Open Pole STRUCTURE 8   Open Pole STRUCTURE 9   Open Pole STRUCTURE 1   Open Pole STRUCTURE 2   Open Pole STRUCTURE 2   Open Pole STRUCTURE 2   Open Pole STRUCTURE 3   Open Pole STRUCTURE 2   Open Pole STRUCTURE 3   Open Pole STRUCTURE 2   Open Pole STRUCTURE 3   Open Pole STRUCTURE 4   Open Pole STRUCTURE 5   Open Pole STRUCTURE 6   Open Pole ST	•
Access: HOST Tech ID/Equip #: Lat: Long:  023/278 WOOD POLE STRUCTURE 40826545 2 POLE SUSP FOOT ONLY  1   loc inspect d this patrol Notes: '02 Survey: K002008  39.328800000000 -120.3884840000  203/280 WOOD POLE STRUCTURE 40618849 3 POLE SINGLE VERTICAL FOOT ONLY  1   loc inspect d this patrol Notes: '02 Survey: K002011  1   loc inspect d this patrol Notes: '02 Survey: K002011  39.328553000000  203/281 WOOD POLE STRUCTURE 4054687 2 POLE SUSP FOOT ONLY  1   locmpleted/no problems   loc Survey: K002011   loc survey: K002011   loc survey: K002011   loc survey: K002012    loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002012   loc survey: K002013	
HOST Tech ID/Equip #: Lat: Long:  023/278 WOOD POLE STRUCTURE 40826545 2 POLE SUSP FOOT ONLY  39.328800000000 -120.3884840000  023/280 WOOD POLE STRUCTURE 40618849 3 POLE SINGLE VERTICAL FOOT ONLY  39.328553000000 -120.3847950000  023/281 WOOD POLE STRUCTURE 4054857 1   completed/no problems   Total # of Attachments:   Completed/no problems   T	·
Lat: Long:  023/278 WOOD POLE STRUCTURE  40826545 2 POLE SUSP	
Long:   O23/278 WOOD FOLE STRUCTURE   Completed/no problems   Total # of Attachments:   O2 Survey: K002008   O23/280 WOOD FOLE STRUCTURE   Completed/no problems   Total # of Attachments:   O2 Survey: K002008   O23/280 WOOD FOLE STRUCTURE   Completed/no problems   Total # of Attachments:   O2 Survey: K002008   O23/280 WOOD FOLE STRUCTURE   Completed/no problems   Total # of Attachments:   O2 Survey: K002010   O23/280 WOOD FOLE STRUCTURE   Completed/no problems   Total # of Attachments:   O2 Survey: K002011   O23/281 WOOD FOLE STRUCTURE   Completed/no problems   O23/281 WOOD FOLE STRUCTURE   Completed/no problems   Complet	
1	
2 POLE SUSP	
I	
Notes: '02 Survey: K002008	
39.328800000000 -120.3884840000  023/280 WOOD POLE STRUCTURE 40618849	
-120.3884840000  023/280 WOOD POLE STRUCTURE	
Completed/no problems	
3 POLE SINGLE VERTICAL   [ ] pre-existing cond chked   [ ] not inspect this patrol   Notes: '02 Survey: K002011   Notes: '02 Survey: K002011   Notes: '02 Survey: K002011   Notes: '02 Survey: K002011   Notes: '02 Survey: K002012   Notes: '02 Survey: K002013   Notes: '02 Surve	
Inot inspetd this patrol	
Notes: '02 Survey: K002011	
-120.3847950000  023/281 WOOD POLE STRUCTURE  40594587  2 POLE SUSP  FOOT ONLY  1 Inot inspect this patrol  Notes: '02 Survey: K002012  39.328129000000  -120.3832720000  023/282A SINGLE WOOD POLE  40660471  3 POLE DOUBLE VERTICAL  [ ] completed/no problems [ ] lompleted/no problems [ ] lotal # of Attachments:     39.327543000000  -120.3810110000	
-120.3847950000  023/281 WOOD POLE STRUCTURE  40594587  2 POLE SUSP  FOOT ONLY  1 Inot inspect this patrol  Notes: '02 Survey: K002012  39.328129000000  -120.3832720000  023/282A SINGLE WOOD POLE  40660471  3 POLE DOUBLE VERTICAL  [ ] completed/no problems [ ] lompleted/no problems [ ] lotal # of Attachments:     39.327543000000  -120.3810110000	
Completed/no problems   Total # of Attachments:	
[ ] not inspctd this patrol  Notes: '02 Survey: K002012  39.328129000000  -120.3832720000  023/282A SINGLE WOOD POLE 40660471	
[ ] not inspctd this patrol  Notes: '02 Survey: K002012  39.328129000000  -120.3832720000  023/282A SINGLE WOOD POLE 40660471	
Notes: '02 Survey: K002012  39.328129000000  -120.3832720000  023/282A SINGLE WOOD POLE  40660471	
-120.3832720000  023/282A SINGLE WOOD POLE 40660471 3 POLE DOUBLE VERTICAL [   pre-existing cond chked   [   lnot inspetd this patrol   Notes: '02 Survey: K002013  39.327543000000 -120.3810110000	
023/282A SINGLE WOOD POLE 40660471 [lcompleted/no problems   Total # of Attachments:  [lcompleted/new finding(s)   [lpre-existing cond chked   [lnot inspetd this patrol   Notes: '02 Survey: K002013  39.327543000000   -120.3810110000	
40660471 [	
3 POLE DOUBLE VERTICAL [ ] pre-existing cond chked [ ] not inspetd this patrol Notes: '02 Survey: K002013  39.327543000000 -120.3810110000	
[]not inspctd this patrol Notes: '02 Survey: K002013  39.327543000000 -120.3810110000	
Notes: '02 Survey: K002013 39.327543000000 -120.3810110000	
39.327543000000 -120.3810110000	
-120.3819110000	
023/282B SINGLE WOOD POLE   completed/no problems   Total # of Attachments:	
42572841 [] completed/new finding(s)	
ANGLE 0-30 DEGREES [ ]pre-existing cond chked .	
[ ]not inspetd this patrol	
Notes: '02 Survey: K002115	
39.327514000000	
-120.3810980000	
023/282C SINGLE WOOD POLE //completed/no problems Total # of Attachments:	
42572842 (lcompleted/new finding(s)	
ANGLE 0-30 DEGREES [ ]pre-existing cond chked	
[] not inspctd this patrol	
Notes: '02 Survey: K002115	
39.327501000000	1
-120.3811020000	
023/283A SINGLE WOOD POLE   Completed/no problems   Total # of Attachments:	1
40650166 [ ] completed/new finding(s)	۳
3 POLE SINGLE VERTICAL [ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR [] not inspctd this patrol	
Notes: '02 Survey: K002014	
39.325874000000	
-120.3812490000	
023/283B SINGLE WOOD POLE	
42572843 [] completed/new finding(s)	
ANGLE 0-30 DEGREES [ ]pre-existing cond chked	
( )not inspetd this patrol	
Notes: '02 Survey: K002115	
39.325875000000	
-120.3811870000	

Inspector Name : SEAR C

Date Inspected : 7-19-13

Funct Loc: ETL.1450.FOLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	14th almont a f
Desc of fech ID  Equip #	Tuspection Kesuit	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Notes	
Long:		
023/283C SINGLE WOOD POLE	I Verraleted for each least	Imperial to a second se
42572844	//completed/no problems	Total # of Attachments:
ANGLE 0-30 DEGREES	[]completed/new finding(s) []pre-existing cond chked	
ANGUE 0-30 DEGREES	[ ]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.325882000000	Roces: -02 Salvey: Rouzilis	
-120.3812820000		
024/284 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40590218	[]completed/new finding(s)	Acces & or Medicinicates;
2 POLE SUSP	[ ] pre-existing cond chked	, , ,
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	31 @ 920
	Notes: '02 Survey: K002015	
39.325125000000	The state of the s	
-120.3817100000		·
024/285 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
40586210	[]completed/new finding(s)	,
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002016	
39.324265000000		
-120.3822120000		
024/286A SINGLE WOOD POLE		Total # of Attachments:
40660475	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002017	
39.323695000000		
-120.3825750000		
024/286B SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
42572845	[ ]completed/new finding(s)	
ANGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.323671000000		
-120.3826420000	/	
024/286C SINGLE WOOD FOLE	//completed/no problems	Total # of Attachments:
42572846	[ ]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.323655000000		
-120.3826940000		
024/287 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments: 1
10650168		DIST-0310456 1
POLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
FOOT ONLY	[]not inspctd this patrol	
20. 30300700000	Notes: '02 Survey: K002018	
39.323007000000		
120.3824000000	I describe a description of the second of th	maked W. S. Akkersky
24/288 WOOD POLE STRUCTURE		Total # of Attachments: 1
0908634 POLE SUSP	-	DIST-0310456 1
OOT ONLY	[ ]pre-existing cond chked	
OOF OWNT	[ ]not inspctd this patrol   Notes: '02 Survey: K002019	
9.322625000000	Modes. Oz Barvey: Kuuzurs	
120.3816340000		
	1	

Inspector Name : Serrico

Date Inspected : 7-16-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		•
Long:		
024/289 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments: 1
40764780	[]completed/new finding(s)	DIST-0310456 1
3 FOLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002020	
39.32198300000		· ·
-120.3807060000		
024/290 WOOD POLE STRUCTURE	//lcompleted/no problems	Total # of Attachments:
40755605	[]completed/new finding(s)	· i
2 POLE SUSP	[]pre-existing cond chked	·
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
MEDIUM EQP(ABRIAG DIFI)DING IX	Notes: '02 Survey: K002021	
30 321054000000	Modes. Oz Satvey. Modesat	
39.321054000000	,	
-120.3789710000		Total # of Attachments: 1
024/291A SINGLE WOOD POLE	[]completed/new finding(s)	CELL-UNKNOWN 1
40810280	[ ]pre-existing cond chked	CAND CARROLL 2
3 POLE DOUBLE VERTICAL	[ ]not inspetd this patrol	
MEDIUM EQP(AERIAL LIFT;LINE TR	Notes: '02 Survey: K002022	
	Notes: '02 Survey: K002022	
39.320576000000		
-120.3781690000	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Impto 1 # of 2the America
024/291B SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
42572875	[]completed/new finding(s)	
DOUBLE DEAD END	[]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.320573000000		
-120.3782420000		
024/291C SINGLE WOOD POLE	] completed/no problems	Total # of Attachments:
42572876	[ ]completed/new finding(s)	
DOUBLE DEAD END	[ ]pre-existing cond chked	
	[ ]not inspctd this patrol	
	Notes: '02 Survey: K002115	
39.320564000000		
-120.3783040000		
024/292 WDOD POLE STRUCTURE	[] completed/no problems	Total # of Attachments:
40818183	[ ]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP{AERIAL LIFT; LINE TR	[ ] not inspctd this patrol	
	Notes: '02 Survey: K002023	
39.319361000000		
-120.3781990000		
024/293 WOOD POLE STRUCTURE	]completed/no problems	Total # of Attachments:
40862284	[ ]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002024	
39.318715000000		
-120.3782590000		
024/294 WOOD POLE STRUCTURE	completed/no problems	Total # or Attachments:
40866067	[ ] completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
FOOT ONLY	[ ]not inspctd this patrol	
	Notes: '02 Survey: K002025	
39.3172390000 <b>00</b>	-	
-120.3780760000		

Inspector Name : SEARD

Date Inspected : 7-16-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	111010000101111111111111111111111111111	Attachment Type/Owner Listed
Equip # Framing Config		
Access:		
OST Tech ID/Equip #:	Notes	
	Noces	
Lat:		
Long:		Total # of Attachments:
24/295 WOOD POLE STRUCTURE		Total # of Accasimencs:
0590221	[]completed/new finding(s)	
POLE SUSP	[]pre-existing cond chked	
TOOT ONLY	[]not inspetd this patrol	
	Notes: '02 Survey: K002026	
39.316557000000		
120.3779590000		
24/296A SINGLE WOOD POLE	]completed/no problems	Total # of Attachments:
0594971	[]completed/new finding(s)	
POLE SINGLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspctd this patrol	
	Notes: '02 Survey: K002157	
9.315472000000		
120.3777350000	·	
24/296B SINGLE WOOD POLE	]completed/no problems	Total # of Attachments:
2572847	[ ]completed/new finding(s)	
ANGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[ ] not inspetd this patrol	
	Notes: '02 Survey: K002115	
9.315420000000		
120.3777580000		
24/296C SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
2572848	[]completed/new finding(s)	
NGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: 102 Survey: K002115	1
9.315422000000		
120.3778010000		
24/297 WOOD POLE STRUCTURE	Dicompleted/no problems	Total # of Attachments:
0671549	[]completed/new finding(s)	
POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	-
EDITOR EQF (MERING DIFF, MARIE IN	Notes: '02 Survey: K002158	
9.314560000000	The same of the sa	
120.3764180000	/	
25/298 WOOD POLE STRUCTURE	//lcompleted/no problems	Total # of Attachments:
	[]completed/new finding(s)	
0618855	[]pre-existing cond chked	
POLE SUSP	[] not inspetd this patrol	
EDIUM EQP(AERIAL LIFT;LINE TR	Notes: '02 Survey: K002159	
	Notes: .02 Survey: K002159	
9.313719000000		
120.3752140000	1	Total # of Attachments:
25/299 WOOD POLE STRUCTURE		
<b>05</b> 90 <b>178</b>	[]completed/new finding(s)	
POLE SUSP	[]pre-existing cond chked	
EDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
	Notes: '02 Survey: K002160	
9.312882000000		
120.3739730000		
25/300 WOOD POLE STRUCTURE	Completed/no problems	Total # of Attachments:
0671553	[]completed/new finding(s)	
POLE SUSP	()pre-existing cond chked	
EDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
	Notes: '02 Survey: K002161	
0.31313000000		
9.312138000000		

Inspector Name : __ Date Inspected : ___

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Desc of Tech ID	Inspection Result	Attachments #
	Imprection Konda	Attachment Type/Owner Listed
Equip #		Actacimient Type/owner Tipeca
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	·
Lat:	•	
Long:		
025/301 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
I .	[]completed/new finding(s)	
40654849		
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002162	
39.311308000000		
-120.3715400000		
025/302A SINGLE WOOD POLE	//lcompleted/no problems	Total # of Attachments:
40756991	[ ]completed/new finding(s)	
1	[]pre-existing cond chked	
2 POLE SUSP		
MEDIUM EOP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002163	
39.310653000000		
-120.3705210000	/	
025/302B SINGLE WOOD POLE	// ]completed/no problems	Total # of Attachments:
42572849	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
ANGLE 0-30 DEGREES	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
	Moceat .05 Survey: W005119	
39.31069000000		
-120.3705410000		
025/302C SINGLE WOOD POLE	/ ]completed/no problems	Total # of Attachments:
42572850	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
	10000.	
39.310531000000		
-120.3705550000		Total # of Attachments:
025/303 WOOD POLE STRUCTURE	completed/no problems	YOUAL # OF Accacimments:
40765060	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspctd this patrol	
-	Notes: '02 Survey: K002164	•
39.3104430 <b>0</b> 0000		
1		•
-120.3688980000	]completed/no problems	Total # of Attachments:
025/304 WOOD POLE STRUCTURE		IDCAL W DI ACCACIMENTO.
40815055	[]completed/new finding(s)	
3 POLE TRAMP DOUBLE DEAD END	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT;LINE TR	[ ] not inspctd this patrol	
	Notes: '02 Survey: K002165	
39.310285000000		
-120.3675190000		· ·
025/305 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
1	[]completed/new finding(s)	
40812966	[]pre-existing cond chked	
2 POLE SUSP	[] not inspetd this patrol	
MEDIUM EQP(AERIAL LIFT; LINE TR		
	Notes: '02 Survey: K002166	
39.310196000000		
-120.3660490000	/	
025/306 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40871457	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
MEDION DOS (MEKIND DIEI) DIME IK	Notes: '02 Survey: K002167	
	TOUGHT US MILITON, INVESTOR	·
39.310034000000		
-120 3637370000		

Page 53

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name : SEARD

Date Inspected : 7-16-13

High Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Notes	
Long:		
025/307 WOOD POLE STRUCTURE	[/completed/no problems	Total # of Attachments:
·	[]completed/new finding(s)	TOTAL TOL ACCOMMENSOR.
40869623	[]pre-existing cond chked	
STEEL X ARM	[] not inspetd this patrol	
MEDIUM EQP(AERIAL LIFT; LINE TR		
	Notes: '02 Survey: K002168 snow cat in winter	
39.309917000000	snow cac in winter	
-120.3619200000	/ ]completed/no problems	Total # of Attachments:
025/308 WOOD POLE STRUCTURE	1T	Total # Or Actachments:
40597138	[]completed/new finding(s)	
2 POLE SUSP	( lpre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002169	
39.30978900000		
-120.3602080000		
025/309 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40590183	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ] not inspctd this patrol	
	Notes: '02 Survey: K002170	
39.30969900000		
-120.3587530000		
026/310 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40597141	[]completed/nsw finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002171	
39.309578000000		
-120.3569460000		
026/311A SINGLE WOOD POLE	/ ] completed/no problems	Total # of Attachments:
40590181	[]completed/new finding(s)	
3 POLE SINGLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	( )not inspetd this patrol	
	Notes: '02 Survey: K002172	
39.309558000000		
-120.3554180000		
026/311B SINGLE WOOD POLE	/ ]completed/no problems	Total # of Attachments:
42572851	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	· · · · · · · · · · · · · · · · · · ·
39.309454000000		
-120.3554490 <b>000</b>		
026/311C SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
42572852	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	·
	[]not inspetd this patrol	
	Notes: '02 Survey: KC02115	
39.309436000000	1	
-120.3554580000	,	
026/312 WOOD POLE STRUCTURE	/ ]completed/no problems	Total # of Attachments:
40668907	[]completed/new finding(s)	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[] not inspetd this patrol	
MODIUM DOF (ADRIAN MIRI; DING TR	Notes: '02 Survey: K002173	
20 20007000000	40.00 vey. 2002113	
39.309007000000		
-120.3539780000		

Inspector Name : SERRO

Date Inspected : 7-16-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
	THSPECTION RESULT	
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	· · · · · · · · · · · · · · · · · · ·
Lat:		
Long:		
026/313 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40660176	[ ]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT;LINE TR	[ ]not inspctd this patrol	
1	Notes: '02 Survey: K002174	•
39.308520000000		
-120.3524420000	,	
026/314A SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
40756993	[]completed/new finding(s)	
	-	
3 POLE SINGLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ] not inspetd this patrol	
	Notes: '02 Survey: K002175	
39.308019000000	/	
-120.3507330000		
026/314B SINGLE WOOD POLE	/ ]completed/no problems	Total # of Attachments:
42572854	[ ]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
reges 0-30 perces	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
	Notes: '02 Survey: KD02115	
39.307983000000	/	
-120.3506990000		
026/314C SINGLE WOOD POLE	//Icompleted/no problems	Total # of Attachments:
42572855	[ ]completed/new finding(s)	
ANGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.307938000000		
-120.3507200000		
026/315 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40771054	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002176	
39.308214000000		
-120.3488250000		
026/316 WOOD POLE STRUCTURE	]completed/no problems	Total # of Attachments:
•	[]completed/new finding(s)	10001 # 01 PRECOGNICION
40815057	_	
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002177	
39.30852 <b>0</b> 000000		
-120.3470350000		
026/317 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40809771	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
manufacture are typical are	Notes: '02 Survey: K002178	
39.308738000000	Noces: 02 parvey: Nou2116	
		<b>'</b>
-120.3452100000		
026/318 WOOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40866626	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	·
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002179	
39.309291000000	•	
-120.3432100000		

Inspector Name : SEARO

Date Inspected : 2-16-13

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		The state of the s
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		•
026/319 WOOD POLE STRUCTURE		Total # of Attachments:
40864944	[]completed/new finding(s)	Total # Of Actachments:
2 POLE SUSP	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	
MEDICA SYPIASATAN NEPIJINE IR		
39.30951200000	Notes: '02 Survey: K002180	
	1	
-120.3422220000	1	
026/320 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40597145	completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002181	
39.309802000000	1000	
-120.3409380000	HOTO SPLIET IN	GUY WIRE
027/321 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40605262	[ ]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002182	
39.310389000000		
-120.3397730000		
027/322 LATTICE STEEL TOWER	/ lcompleted/no problems	Total # of Attachments:
40590184	[ ]completed/new finding(s)	H 47 110000011011001
3 POLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002183	
39.310777000000	Acces: 02 Bulley: Roozins	
-120.3384170000	1	·
027/323 LATTICE STEEL TOWER	(//completed/no problems	
40671557		Total # of Attachments:
OOUBLE DEAD END		
FOOT ONLY	[ ]pre-existing cond chked	
FOOT ONLY	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002184	
39.31088500000	0 - 0	
120.3380830000	BENT DAMPER	
027/324 WOOD POLE STRUCTURE	/ completed/no problems	Total # of Attachments:
0659727	[]completed/new finding(s)	•
POLE SUSP	[ ]pre-existing cond chked	
EDIUM EQP(AERIAL LIFT; LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002185	
9.311412000000		
120.3351900000	1/	
27/325 WOOD POLE STRUCTURE	i   completed/no problems	Total # of Attachments: 1
0755704	[ ]completed/new finding(s)	DI\$T-0310456 1
POLE SUSP	[ ]pre-existing cond chked	
EDIUM EQP(AERIAL LIFT;LINE TR	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002186	
9.311787000000		
120.3336460000		
7/326A SINGLE WOOD POLE		Total # of Attachments:
7752050	[] completed/new finding(s)	
POLE SINGLE VERTICAL	[]pre-existing cond chked	
OOT ONLY	[] not inspetd this patrol	
	Notes: '02 Survey: K002187	
9.312138000000	Noces: '02 Survey: KUU2187	
20.3322690000		
2011111 0 3 N N N N N N N N N N N N N N N N N N	4	

Page 56

Funct Loc : ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE

Order : 41815880 PATR/INSP 10058 DRUM-SUMMIT #2

Inspector Name : SEPRO 7-16-13

High Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		'
Access:		
HOST Tech ID/Equip #:	Notes	
	Mores	
Lat:		
Long:		
027/326B SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
42572856	[ ]completed/new finding(s)	
ANGLE 0-30 DEGREES	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.31210800000		
-120.3322420000		
027/326C SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
42572857	[]completed/new finding(s)	
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
Mighin 0-30 photonic	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002115	
39.312074000000		
-120.3322000000		
027/327 WOOD POLE STRUCTURE	[/]completed/no problems	Total # of Attachments:
40820272	[ ]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[ ]pre-existing cond chked	
	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002188	
39.312772000000	_	· ·
-120.3318620000		
027/328 WDOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40821391	[]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
	[]not inspetd this patrol	
FOOT ONLY		
	Notes: '02 Survey: K002189	
39.313083000000		
-120.3315930000		
027/329 WOOD POLE STRUCTURE	[]completed/no problems	Total # of Attachments:
40865431	[ ]completed/new finding(s)	•
2 POLE SUSP	[ ]pre-existing cond chked	
FDOT ONLY	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002190	
39.31382900000		L.
-120.3312100000		
027/330 WDOD POLE STRUCTURE	//completed/no problems	Total # of Attachments:
40870576	[ ]completed/new finding(s)	
3 POLE DOUBLE VERTICAL	[]pre-existing cond chked	
FOOT ONLY	[] not inspetd this patrol	
FOOT ONE!	Notes: '02 Survey: K002191	
	Motes: .02 Survey: K002191	
39.314946000000		
-120.3304990000		Improduce to the book of the contract of the c
027/331 WOOD POLE STRUCTURE	completed/no problems	Total # of Attachments:
40597148	[]completed/new finding(s)	
2 POLE SUSP	[ ]pre-existing cond chked	
FOOT ONLY	[ ]not inspetd this patrol	
	Notes: '02 Survey: K002192	
39.315844000000		
-120.3298190000		<u> </u>
027/332 LATTICE STEEL TOWER SW 2	completed/no problems	Total # of Attachments:
40579656	[ ]completed/new finding(s)	
FIELD SWITCH STRUCTURE	[]pre-existing cond chked	
FOOT ONLY	[ ]not inspetd this patrol	
<del></del>	Notes: '02 Survey: K002027	
39.316215000000	122.27.11.72.2	
-120.3295100000		
200.000000		

Page 57.

Inspector Name : ____ Date Inspected : _____

: 41815880

Funct Loc: ETL.1450.POLE.WOOD 10058 DRUM-SUMMIT #2-WOOD POLE PATR/INSP 10058 DRUM-SUMMIT #2

High Impact

Detailed Ground Inspections

Desc of Tech ID Equip # . Framing Config Access: HOST Tech ID/Equip #:	Inspection Result	Attachments # Attachment Type/Owner Listed
Lat: Long:		
028/333 WOOD POLE STRUCTURE 40597150 2 POLE DOUBLE DEAD END FOOT ONLY	[]pre-existing cond chked []not inspctd this patrol	
39.317122000000 -120.3291600000	Notes: '02 Survey: K002028	

30'@ 950

105385147	105178652	105971322	105178720	105071300	105385144	105385143	105385140	106025479	106025478	105247662	106059169	106059290	105385129	106059167	106059229	106059228	106059166	106059227	106059165	106059164	106059163	106059077	105247629	105994441	106059226	105522440	105971288	105971287	105178716	106027941	Notification	
07/30/2011 DRUM-SUMMIT #2 5/066 REPL POLE "LFT"	DRUM-SUMMIT #2	03/14/2012 DRUM-SUMMIT #2 005/064 REPL POLE "CIR"	- 1	DRUM-SUMMIT #2	005/061C	005/061B	0//30/2011 DRUM-SUMMIT #2 005/061A REPL POLE	04/23/2012 DRUM SUMMIT #2 005/059C REPLPOLE	04/23/2012 DRUM SUMMIT #2 005/059B REPL POLE	09/10/2010 DRUM SUMMIT #2 005/059A REPL POLE	05/22/2012 DRUMM-SUMMIT #2 3/43 RPL POLE LEFT/NERC	05/22/2012 DRUMM-5UMMIT #2 3/43 RPL POLE RIGH/NERC	07/30/2011 DRUM-SUMMIT #2 003/039C REPL POLE	05/22/2012 DRUMM-SUMMIT #2 3/35 RPL POLE LEFT/NERC	05/22/2012 DRUMM-SUMMIT #2 3/35 RPL POLE RIGH/NERC	05/22/2012 DRUMM-5UMMIT #2 2/33 RPL POLE RIGH/NER	05/22/2012 DRUMM-SUMMIT #2 2/33 RPL POLE/ LEFT/NER	05/22/2012 DRUMM-SUMMIT #2 2/32 RPL POL RIGHT. NERC	05/22/2012 DRUMM-5UMMIT #2 2/32 RPL POLE LEFT/NERC		05/22/2012 DRUMM-SUMMIT #2 1/15B RPL POLE/NERC PROJ	05/22/2012 DRUMM-5UMMIT #2 1/15a RPL POLE/NERC PROJ	09/13/2010 DRUM 5UMMIT #2 001/013 REPL POLE "CTR"	03/29/2012 DRUM SUMMIT #2 001/013 REPL POLE "LFT"	10/19/2011 DRUMM-SUMMIT #2 0/09 RPL POLE RIGT/NERC	10/19/2011 DRUMM-SUMMIT #2 0/09 RPL POLE LEFT/NERC	03/14/2012 DRUM-SUMMIT #2 000/008 REPL POLE "RT"	03/14/2012 ORUM-5UMMIT #2 000/008 REPL POLE "LFT"	08/18/2010 DRUM-SUMMIT #2 000/008 REPL POLE "CTR"	04/24/2012 DRUM-SUMMIT #2 CORRECT GROUND CLERANCE	Notif.date Description	
005/066 WOOD POLE STRUCTURE	005/065 WOOD POLE STRUCTURE	005/064 WOOD POLE STRUCTURE	005/064 WOOO POLE STRUCTURE	005/064 WOOO POLE STRUCTURE	005/061C SINGLE WOOD POLE	005/061B SINGLE WOOD POLE	005/061A SINGLE WOOD POLE	005/059C SINGLE WOOD POLE	005/059B SINGLE WOOD POLE	005/059A 5INGLE WOOD POLE	003/043 WOOD POLE STRUCTURE	003/043 WOOO POLE 5TRUCTURE	003/039C 5INGLE WOOD POLE	003/035 WOOD POLE STRUCTURE	003/035 WOOD POLE STRUCTURE	002/033 WOOD POLE STRUCTURE	002/033 WOOO POLE STRUCTURE	002/032 WOOD POLE STRUCTURE	002/032 WOOD POLE STRUCTURE	001/015C SINGLE WOOD POLE	001/015B 5INGLE WOOD POLE	001/015A SINGLE WOOD POLE	001/013 WOOD POLE STRUCTURE	001/013 WOOD POLE STRUCTURE	000/009 WOOO POLE STRUCTURE	000/009 WOOD POLE STRUCTURE	000/008 WOOO POLE STRUCTURE	000/008 WOOD POLE STRUCTURE	000/008 WOOD POLE STRUCTURE		Description	
40806531	40806531	40828476	40828476	40828476	42572760	42572759	40669056	42572758	42572757	40586197	40869615	40869615	42572868	40586192	40586192	40603786	40603786	40862026	40862026	42572746	42572745	40668112	40604671	40604671	40862024	40862024	40878342	40878342	40878342		Equipment	
ETL.1450 07/31/2013 09/11/2010 eTL.1450 07/31/2013 07/30/2011	03/14/2014	11/30/2013	$\neg$	_	$\overline{}$	ETL.1450 07/31/2013			$\neg$		$\neg \Gamma$	-	$\neg$	12/31/2013	-		$\neg$		$\neg$			ETL.1450 12/31/2013	ETL.1450 10/31/2013 09/13/2010	FTI 1450 11/30/2014	$\neg$	$\neg$	$\neg$		^-+	50	al Loc. End	Function Required
09/11/2010 07/30/2011	03/14/2012	09/11/2010	03/14/2012	09/11/2010	07/30/2011		07/30/2011		- 4	- 1	$\neg$	05/32/2012		05/22/2012	05/22/2012	12/31/2013 05/22/2012	- 1-		$\neg$		$\overline{}$	05/22/2012	09/13/2010			$\neg$		$\neg$	$\neg$	_	date	Reference

105170073	106024087	106024088	105385171	105385170	10S385148	106059202	106059292	105178658	105178718	105972072	10S256795	105247737	105178710	105178655	105178722	105972070	105971729	105178723	105971329	105247736	105991559	105991558	105991555	105247735	105971324	105971325	105178654	105991553	105247733	106089291	106059200	106024081
	04/23/2012 DRUM-5UMMIT #2 10/127 REPL POLE "LFT"	04/23/2012 DRUM-SUMMIT #2 10/127 REPL POLE "CTR"	07/30/2011 DRUM-5UMMIT #2 10/121C REPL POLE	07/30/2011 DRUM-5UMMIT #2 10/121B REPL POLE	07/30/2011 DRUM-5UMMIT #2 10/121A REPL POLE	05/22/2012 ORUMM-5UMMIT #2 10/118 RPL POLE LEFT/NER	05/22/2012 DRUMM-5UMMIT #2 10/118 RPL POLE RIGH/NER	08/07/2010 DRUM-5UMMIT #2 009/111 REPL POLE	08/18/2010 DRUM-5UMMIT #2 009/111B REPL POLE	03/14/2012 DRUM 5UMMIT #2 009/109 REPL POLE "LFT"	08/04/2010 DRUM 5UMMIT #2 009/109 REPL POLE "RT"	09/09/2010 DRUM 5UMMIT #2 009/109 REPL POLE "CTR"	08/07/2010 DRUM-5UMMIT #2 009/102A REPL POLE	08/07/2010 DRUM-5UMMIT #2 008/099C REPL POLE	09/11/2010 DRUM-5UMMIT #2 008/097 REPL POLE "CTR"	03/14/2012 DRUM-5UMMIT#2 008/097 REPL POLE "RT"	03/14/2012 DRUM-5UMMIT #2 008/097 REPL POLE "LFT"	09/11/2010 DRUM-5UMMIT #2 007/088 REPL POLE "RT"	03/14/2012 DRUM-5UMMIT #2 007/088 REPL POLE "LFT"	09/09/2010 DRUM 5UMMIT #2 007/086C REPL POLE	03/29/2012 DRUM 5UMMIT #2 007/086B REPL POLE	03/29/2012 DRUM 5UMMIT#2 007/086A REPL POLE	03/29/2012 DRUM 5UMMIT #2 007/085 REPL POLE "RT"	09/08/2010 DRUM 5UMMIT #2 007/085 REPL POLE "LFT"	03/14/2012 DRUM-5UMMIT #2 007/081 REPL POLE "CTR"	03/14/2012 ORUM-5UMMIT #2 007/081 REPL POLE "RT"	09/11/2010 DRUM-5UMMIT #2 007/081 REPL POLE "LFT"	09/09/2010 DRUM 5UMMIT #2 007/080 REPL POLE "RT"	09/09/2010 DRUM SUMMIT #2 007/080 REPL POLE "LFT"	05/22/2012 DRUMM-5UMMIT #2 6/74 RPL POLE RIGH/NERC	OS/22/2012 DRUMM-SUMMIT #2 6/74 RPL POLE LEFT/NERC	04/23/2012 DRUM-5UMMIT#2 5/066 REPL POLE "RT"
012/140 WOOD POLE STRUCTURE	010/127 WOOD POLE STRUCTURE	010/127 WOOD POLE STRUCTURE	010/121C SINGLE WOOD POLE	010/121B SINGLE WOOD POLE	010/121A SINGLE WOOO POLE	010/118 WOOD POLE STRUCTURE	010/118 WOOD POLE STRUCTURE	009/111 WOOD POLE STRUCTURE	009/111 WOOD POLE STRUCTURE	009/109 WOOD POLE STRUCTURE	009/109 WOOO POLE STRUCTURE	009/109 WOOD POLE STRUCTURE	009/102A SINGLE WOOD POLE	008/099C 5INGLE WOOD POLE	008/097 WOOD POLE STRUCTURE	008/097 WOOD POLE STRUCTURE	008/097 WOOD POLE STRUCTURE	007/088 WOOO POLE STRUCTURE	007/088 WOOD POLE STRUCTURE	007/086C SINGLE WOOD POLE	007/086B SINGLE WOOD POLE	007/086A SINGLE WOOD POLE	007/085 WOOD POLE STRUCTURE	007/085 WOOD POLE STRUCTURE	007/081 WOOD POLE STRUCTURE	007/081 WOOD POLE STRUCTURE	007/081 WOOD POLE STRUCTURE	007/080 WOOD POLE STRUCTURE	007/080 WOOD POLE STRUCTURE	006/074 WOOD POLE STRUCTURE	006/074 WOOD POLE STRUCTURE	005/066 WOOD POLE STRUCTURE
40593971	40586198	40586198	42572785	42572784	40752039	40660433	40660433	40876990	40876990	40826559	40826559	40826559	40618835	42572772	40828480	40828480	40828480	40862276	40862276	42572766	42572765	40810270	40755597	40755597	40602585	40602585	40602585	40618817	40618817	40771042	40771042	40878351
ETL.1450.	ETL.1450	ETL.1450.		ETL.1450.	ETL.1450	ETL.1450	ETL.1450.	ETL.1450	ETL.1450.	ETL.1450.	ETL.1450.	ETL.1450.	ETL.1450.	ETL.1450.	ETL.1450.	ETL.1450.	1 1	ETL.1450.	ETL.1450	ETL.1450	ETL.1450	ETL.1450.	ETL.1450	ETL.1450.	ETL.1450.	ETL.1450.	ETL.14S0.	ETL.1450.	ETL.1450		ETL.1450	ETL.1450.
11/30/2013	04/30/2014	04/30/2014	07/31/2013	07/31/2013	07/31/2013	12/31/2013	12/31/2013	11/30/2013	11/30/2013	ETL.1450 03/14/2014	10/31/2013	10/31/2013	11/30/2013	11/30/2013	11/30/2013	03/14/2014	03/14/2014	11/30/2013	03/14/2014	10/31/2013	11/30/2014 03/29/2012	11/30/2014 03/29/2012	11/30/2014	10/31/2013	03/14/2014	03/14/2014	ETL.14S0 11/30/2013 09/11/2010	ETL.1450 11/30/2014 09/09/2010	10/31/2013	12/31/2013	12/31/2013	04/30/2014 04/23/2012
09/04/2010		ETL.1450 04/30/2014 04/23/2012		$\neg$	07/30/2011	05/22/2012	05/22/2012	ETL.1450 11/30/2013 08/07/2010	ETL.1450 11/30/2013 08/18/2010	03/14/2012	08/04/2010	09/09/2010	08/07/2010	11/30/2013 08/07/2010	11/30/2013 09/11/2010	03/14/2014 03/14/2012	03/14/2012	09/11/2010	03/14/2012	09/09/2010	03/29/2012	03/29/2012	03/29/2012	09/08/2010	03/14/2012	03/14/2012	09/11/2010	09/09/2010	10/31/2013 09/09/2010	05/22/2012	05/22/2012	04/23/2012

T77690977	105991664	1051/8/15	10524//55	105343255	106059294	106050304	106059218	106050318	106059215	106059215	106059214	106059212	1060S9211	106059210	106059208	106059206	T06059205	108991609	105178712	105991660	10S247770	105991606	105991607	10602S565	105178714	106025568	105178713	106025564	105247753	106025621	106059293	106059204	
1 05/22/2012 DRUMM-SUMMIT #2 16/198 RPL POLE LEFT/NER	03/29/2012 DRUM-SUMMIT #2 015/187 REPL POLE "LFT"	_	08/21/2010 DRUM SUMMIT #2 15/186A REPL POLE	15.	05/22/2012 ORUMIVI-SUMMIT #2 15/185 RPL POLE RIGH/NER	05/22/2012 DRUMIM-SUMMIT #2 15/184CRPL POLE/NERC PRO	OS/22/2012 URUWIWI-SUMMIT #2 15/184BRPL POLE/NERC PRO	05/22/2012 DRUMMI-SUMMIT #2 15/184ARPL POLE/NERC PRO	2012	2012	2012		0S/22/2012 DRUMM-5UMMIT #2 14/167BRPL POLE/NERC PRO	05/22/2012 DRUMM-5UMMIT #2 14/167ARPL POLE/NERC PRO	0S/22/2012 DRUMM-SUMMIT #2 14/16SCRPL POLE/NERC PRO	0S/22/2012 DRUMM-SUMMIT #2 14/16SBRPL POLE/NERC PRO	0S/22/2012 DRUMM-SUMMIT #2 14/16SARPL POLE/NERC PRO	03/29/2012 DRUM-SUMMIT #2 014/163 REPL POLE "RT"	08/07/2010 DRUM-SUMMIT #2 014/163 REPL POLE "LFT"	03/29/2012 ORUM-SUMMIT #2 014/163 REPL POLE "CTR	09/01/2010 DRUM SUMMIT #2 14/161 REPL POLE "CTR"	03/29/2012 DRUM SUMMIT #2 14/161 REPL POLE "LFT"	03/29/2012 ORUM SUMMIT #2 14/161 REPL POLE "RT"	04/23/2012 DRUM-5UMMIT #2 013/160 REPL POLE "RT"	08/28/2010 DRUM-SUMMIT #2 013/160 REPL POLE "LFT"	04/23/2012 ORUM-5UMMIT #2 013/160 REPL POLE "CTR"	08/07/2010 DRUM-5UMMIT #2 013/156 REPL POLE "LFT"	04/13/2012 ORUM-SUMMIT #2 013/156 REPL POLE "RT"	08/30/2010 DRUM SUMMIT #2 13/153B REPL POLE	04/23/2012 DRUM 5UMMIT #2 13/153A REPL POLE	05/22/2012 DRUMM-5UMMIT #2 13/152 RPL POLE RIGH/NER	05/22/2012 DRUMM-5UMMIT #2 13/152 RPL POLE LEFT/NER	
016/198 WOO		015/187 WOOD POLE STRUCT JRE	015/186A SINGLE WOOD POLE	NER 015/185 WOOD POLE STRUCTURE	/NER 015/185 WOOD POLE STRUCTURE	RC PRO 015/184C SINGLE WOOD POLE				RC PRO 014/1708 SINGLE WOOD POLE	RC PRO 014/170A SINGLE WOOD POLE					RC PRO 014/165B SINGLE WOOD POLE	RC PRO 014/165A SINGLE WOOD POLE			8					7				013/153B SINGLE WOOD POLE	013/153A SINGLE WOOD POLE			
40590198	40702427	40702427	40586203	40608754	40608754	42572814	42572813	40862030	42572805	42572804	40870151	42572799	42572798	40821766	42572797	42572796	40771885	40660441	40660441	40660441	40590185	40S90185	40590185	408S9319	40859319	40859319	40752043	407S2043	42572792	40682561	40602616	40602616	TOUCOLL
TL.1450	_	$\neg$		$\neg \neg$	$\neg$		$\neg \tau$				ETL.1450 12/31/2013		-		_	`	ETL.1450, 12/31/2013		ETL.1450, 11/30/2013	$\neg \tau$	. —	$\neg$	-	$\neg$			$ _{\rm T}$	$\overline{}$		-	$\neg$		LIL.THOULTI/SU/ZUIS
	_			_					$\neg \tau$	$\neg \tau$							$\overline{}$	14 03/29/2012	13 08/07/2010	4 03/29/2012	10/31/2013 09/01/2010	11/30/2014 03/29/2012		$\neg$	$\overline{}$		13 08/07/2010	_		$\neg$		$\neg$	13  09/04/2010



